

HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: Info@huchong.com.sg

Estimate Repair List

23 September 2020

QUOT202009-000034 HHTPCLAIMS20-113

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON RD, #16-01 CITY HOUSE SINGAPORE 068877

Attn: Motor Claims Department

ACCIDENT INVOLVING SLL654H & SHB4731S ON 20/09/2020 ALONG AYE (SLIP RD) TO **LOWER DELTA ROAD AT ABOUT 1155 HOURS**

Insured

HUA HONG PTE LTD

Vehicle Registration No.

SLL654H

Vehicle Make

B.M.W.

Vehicle Model

320I AT ABS D/AB 2WD 4DR GAS/D SR

Vehicle Chassis No.

WBAPG56050NM25454

Policy No.

5116291685-000003

Date of Accident

20/09/2020

Type of Claim: Third Party **Quantity Description Unit Price S\$** Amount S\$ 1 1 / CRU. Rear Bumper 1,336.80 2 2 Rear Bumper Side Retainer (LH/RH) X 47.65 \$ 95.30 - Mec 3 Rear Bumper Clips 5.00 \$ 50.00 Rear Bumper Lower Garnish / (hu 4 1 \$ 169.80 5 1 Rear Bumper Towing Cover / SCR \$ 46.95 6 1 Rear Bumper Reinforcement \$ 460.85 7 1 Rear Bumper Sponge 150.20 8 Rear Reverse Sensor / Shew. 238.05 \$ 476.10 2,786.00 Less 5.% \$ 139.29 2,646,71 To dismantle & change rear bumper, rear reinforcement, Knocking rear end \$ 800.00 panel and all area affected by accident 300 20.00 To perform wire checking \$ To spray rear bumper, rear reinforcement, rear end panel and affected area \$ 800.00 3 4,266.71 7% GST \$ 298.67 4.565.38 Total \$

After pyth phro Suppor (Hab)

Authorised by Claims Dept

Co. Reg. No. 20090030PM

LKK Auto Consultants hence notify

- the Repairer of the following: · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: hughong.com.sg

GST Reg. No. 200900309M

Page 1 of 1