

Estimate Repair List

23 September 2020

QUOT202009-000034 HHTPCLAIMS20-113

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON RD, #16-01 CITY HOUSE SINGAPORE 068877

Attn: Motor Claims Department

ACCIDENT INVOLVING SLL654H & SHB4731S ON 20/09/2020 ALONG AYE (SLIP RD) TO LOWER DELTA ROAD AT ABOUT 1155 HOURS

Insured

HUA HONG PTE LTD

Vehicle Registration No.

SLL654H

Vehicle Make

B.M.W.

Vehicle Model

320I AT ABS D/AB 2WD 4DR GAS/D SR

Vehicle Chassis No.

WBAPG56050NM25454

Policy No.

5116291685-000003

20/09/2020 **Date of Accident** Type of Claim: Third Party S/N **Quantity Description Unit Price S\$** Amount S\$ 1 Rear Bumper 1,336.80 2 2 Rear Bumper Side Retainer (LH/RH) \$ 47.65 \$ 95.30 3 \$ 5.00 \$ 10 Rear Bumper Clips 50.00 4 1 Rear Bumper Lower Garnish \$ 169.80 5 \$ 1 Rear Bumper Towing Cover 46.95 6 1 Rear Bumper Reinforcement \$ 460.85 7 1 Rear Bumper Sponge \$ 150.20 8 2 Rear Reverse Sensor 238.05 \$ 476.10 2.786.00 \$ 139.29 Less 5.% 2.646.71 To dismantle & change rear bumper, rear reinforcement. Knocking rear end \$ 800.00 panel and all area affected by accident To perform wire checking \$ 20.00 To spray rear bumper, rear reinforcement, rear end panel and affected area \$ 800.00 4,266.71 7% GST \$ 298.67

Authorised by Claims Dept

Total \$

4,565.38