



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2008235
INV Date 10/12/2020
Reference CC4/LPC20010310/Ebs3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. GBH 977R
Insured Veh. GBD 5089S
Claim No. 19/20/20/VC05/023702
Policy No. Z19VC05003729
Accident Date 23/09/2020
Inspection Date 15/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC20010310/Ebs3q2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 10-12-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 5089S	Veh. Inspected	GBH 977R
Policy No.	Z19VC05003729	Coverage (\$)	0.00
Claim No.	19/20/20/VC05/023702	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	25/09/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VSKYBAM20Z0152781	Colour	GREY
Odometer	90784	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	DUNLOP	5 mm
L/H Front Tyre	175/70 R14	DUNLOP	5 mm
R/H Rear Tyre	175/70 R14	DUELER	5 mm
L/H Rear Tyre	175/70 R14	DUNLOP	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/09/2020	Inspection Date	15/10/2020
Survey held at	EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD 56 LOYANG WAY #06-07 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 977R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER	DENTED	504.70	504.70
1	FRONT FENDER BRACKET	NOT NECESSARY	38.70	-
1	FRONT FENDER UNDERSHIELD	CRUSHED	194.60	194.60
1	FRONT FENDER SIGNAL LAMP	NOT NECESSARY	66.40	-
1	FRONT QUARTER GLASS MOULDING	NOT NECESSARY	54.50	-
1	HEAD LAMP	BROKEN	446.40	446.40
1	HEADLAMP LOWER COWLING	NOT NECESSARY	362.20	-
1	HEADLAMP LOWER SUPPORT PANEL	NOT NECESSARY	69.90	-
1	FRONT BUMPER	CUT	589.70	589.70
1	FRONT BUMPER RETAINER	BROKEN	25.30	25.30
1	FRONT BUMPER UNDER COVER	NOT NECESSARY	231.00	-
1	WHEEL RIM	NOT NECESSARY	228.80	-
1	LOWER ARM	NOT NECESSARY	192.50	-
2	KNUCKLE ARM @\$357.20	NOT NECESSARY	714.40	-
1	KNUCKLE ARM BEARING	NOT NECESSARY	365.60	-
1	FRONT SHOCK ABSORBER	NOT NECESSARY	252.80	-
	LESS 10% DISCOUNT		-433.75	-176.07
			3,903.75	1,584.63
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT UNDERSHIELD CLIP (SN)	NECESSARY	30.00	10.00
			80.00	40.00
<u>LABOUR</u>				
	TO PANEL BEAT & ALIGN FRONT PORTION ,REMOVE & REPLACE DAMAGED PARTS.		1,000.00	400.00
	TO SPRAY PAINTING FOR REAR PORTIONS & AFFECTED AREAS.		800.00	200.00
	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS.		100.00	30.00
	TO CHECK AND RECTIFY LIGHTING & WIRING .		80.00	30.00
	TO REMOVE & REPLACE UNDERCARRIAGE PARTS.	NOT NECESSARY	400.00	-

Report Ref No. CC4/LPC20010310/Ebs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE TYRE RIM .	NOT NECESSARY	80.00	-
	TO CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	TO CONDUCT DIAGNOSTIC CHECK AND RECTIFY FAULT CODE.		180.00	30.00
			2,760.00	750.00
GRAND TOTAL			6,743.75	2,374.63
RECOMMENDED COST OF REPAIRS				2,374.63

Report Ref No. CC4/LPC20010310/Ebs3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 977R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 977R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

