



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|-----------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 | Cust No/Name /TAN YONG JIAN (CHEN YONGJIAN) Reg No/Reg Date SMF5857B / 19/11/201 Date In/Mileage / 13102 Chassis No MMBSTA13AJH004336 Engine No 3A92UHK0571 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|-------------------|------------|---------------|---------|
| KAX00008 | Credit | 25/09/2020/ 15:50 | QUD | 247 / DonBong | 57779 |
| Description of Goods / Services | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, 1/2 FRONT BONNET, LH FRONT FENDER, LH FRONT DOOR, FRONT BODY KIT LH SIDE SKIRTING, CUT/WELD LH FRONT CHASSIS MEMBER, REPAIR RH FRONT FENDER 1/2 | | | 2250 | | 4050.00 |
| E PNT88000 REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK | | | ? | | 100.00 |
| A 55900099 TOP UP AIR CON GAS AND CHECK A/CON SYSTEM | | | ? | | 80.00 |
| A PNT88100 TO MOUNT VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS ALIGNMENT | | | ? | | 1000.00 |
| A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM | | | | | 30.00 |
| A 54900099 TO CARRY OUT REPAIR ELECTRICAL HARNESS | | | | | 250.00 |
| M SUNDRY APPLY BODY SEALANT | | | 80 | | 160.00 |
| A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | | | | | 120.00 |
| M SUNDRY PERFORM RUST PREVENTION | | | 40 | | 120.00 |
| E PNT98000 PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, FRONT BODY KIT, LH FRONT FENDER, LH FRONT DOOR, RH FRONT FENDER, LH FRONT A PILLAR, LH SIDE SKIRTING PANEL, LH CHASSIS MEMBER, LH FENDER HOUSING AND AFFECTED PORTION | | | 2800 | | 4200.00 |
| A 33900099 RENEW FRONT U/CARRIAGE DAMAGES | | | | | 450.00 |
| A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment | | | | | 120.00 |
| M SUNDRY (Fm LH ty) CUT | | | | | 380.00 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel 65684555 Fax 65691056



ESTIMATE

GST Reg No : NR-8500111-X

Co Reg No : 1977014696

| Invoice Name & Address | Owner Name & Vehicle Info |
|-----------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 | Cust No/Name /TAN YONG JIAN (CHEN YONGJIAN) Reg No/Reg Date SMF5857B / 19/11/201 Date In/Mileage / 13102 Chassis No MMBSTA13AJH004336 Engine No 3A92UHK0571 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---------------------------------|---------------------------|---------------------------------------------------------------------------------------|-----|---------------|--------|------------|-------|--------|
| KAX00008 | Credit | 25/09/2020/ 15:50 | QUD | 247 / DonBong | 57779 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| SUPPLY LH FRONT TIRE | | | | | | | | 30.00 |
| M | SUNDRY | LABOUR RENEW LH FRONT TIRE INCLUDING BALANCING | | | | | | 120.00 |
| E | PNT88000 | REMOVE AND TRANSFER LH FRONT DOOR GLASS, TRIM AND OTHERS ATTACHMENT TO NEW DOOR PANEL | | | | | | 450.00 |
| A | 11900199 | REMOVE AND INSTALL ENGINE TO FACILITATE REPAIR WORK | | | | | | 50.00 |
| M | SUNDRY | SUPPLY FRONT NUMBER PLATE WITH FRAME | | | | | | 50.00 |
| M | SUNDRY | SUNDRIES | | | | | | |
| M | FACE,FR BUMPER | 1 | FR | | 1.00 | 703.00 | 23.00 | 541.31 |
| M | COVER,HEADLAMP SUPT PANEL | 1 | FR | | 1.00 | 62.00 | 23.00 | 47.74 |
| M | GRILLE,FR UNDER | 1 | BR | | 1.00 | 165.00 | 23.00 | 127.05 |
| M | BRACKET,FR BUMPER,LH | 1 | BR | | 1.00 | 13.00 | 23.00 | 10.01 |
| M | BRACKET,FR BUMPER,RH | 1 | BR | | 1.00 | 13.00 | 23.00 | 10.01 |
| M | GARNISH,FR BUMPER,LH | 1 | MIS | | 1.00 | 127.00 | 23.00 | 97.79 |
| M | MARK,THREE-DIA | 1 | MC | | 1.00 | 69.00 | 23.00 | 53.13 |
| M | GRILLE,RADIATOR | 1 | BR | | 1.00 | 554.00 | 23.00 | 426.58 |
| M | HOOD | 1 | DD | | 1.00 | 734.00 | 23.00 | 565.18 |
| M | HINGE,HOOD,LH | 1 | BT | | 1.00 | 56.00 | 23.00 | 43.12 |
| M | HINGE,HOOD,RH | 1 | BT | | 1.00 | 56.00 | 23.00 | 43.12 |
| M | INSULATOR,HOOD | 1 | CRU | | 1.00 | 177.00 | 23.00 | 136.29 |
| M | CLIP,HOOD INSULATOR | 8 | MC | | 8.00 | 3.00 | 23.00 | 18.48 |
| M | LATCH,HOOD | 1 | BT | | 1.00 | 69.00 | 23.00 | 53.13 |
| M | FENDER,FR LH | 1 | DD | | 1.00 | 497.00 | 23.00 | 382.69 |
| M | SHIELD,FR WHEELHOUSE,LH | 1 | MIS | | 1.00 | 98.00 | 23.00 | 75.46 |
| M | CLIP,INNERSHIELD | 13 | MC | | 13.00 | 4.00 | 23.00 | 40.04 |
| M | GARNISH,FR PILLAR,LH | 1 | MIS | | 1.00 | 30.00 | 23.00 | 23.10 |
| M | GARNISH,FR FENDER | 1 | MIS | | 1.00 | 65.00 | 23.00 | 50.05 |
| M | WHEELHOUSE,FR INR LH | 1 | X R | | 1.00 | 364.00 | 23.00 | 280.28 |
| M | PANEL ASSY,FR END | 1 | R | | 1.00 | 1055.00 | 23.00 | 812.35 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

| Invoice Name & Address | Owner Name & Vehicle Info |
|--------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 | Cust No/Name /TAN YONG JIAN (CHEN YONGJIAN) Reg No/Reg Date SMF5857B / 19/11/201 Date In/Mileage / 13102 Chassis No MMBSTA13AJH004336 Engine No 3A92UHK0571 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---------------------------------|------------------------------|-------------------|-----|---------------|--------|------------|-------|---------|
| KAX00008 | Credit | 25/09/2020/ 15:50 | QUD | 247 / DonBong | 57779 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| M | PANEL, HEADLAMP SUPPORT, UPR | X K | | | 1.00 | 65.00 | 23.00 | 50.05 |
| M | SIDEMEMBER ASSY, FR LH | X R | | | 1.00 | 497.00 | 23.00 | 382.69 |
| M | EMBLEM ECO | MC | | | 1.00 | 17.00 | 00.00 | 17.00 |
| M | PANEL, AIR GUIDE, LH | 1 | | | 1.00 | 11.00 | 23.00 | 8.47 |
| M | COVER, ENG ROOM UNDER, FR | 1 | | | 1.00 | 99.00 | 23.00 | 76.23 |
| M | PANEL ASSY, FR DOOR, LH | DO | | | 1.00 | 996.00 | 23.00 | 766.92 |
| M | HINGE, FR DOOR, UPR LH | X | | | 1.00 | 54.00 | 23.00 | 41.58 |
| M | HINGE, FR DOOR, LWR LH | X | | | 1.00 | 54.00 | 23.00 | 41.58 |
| M | TAPE, FR DOOR SASH, LH | MC | | | 1.00 | 29.00 | 23.00 | 22.33 |
| M | COVER, FR DECK, LH | 1 | | | 1.00 | 16.00 | 23.00 | 12.32 |
| M | BODY KIT, ATTRAGE | BR | | | 1.00 | 1643.00 | 00.00 | 1643.00 |
| M | CONDENSER ASSY, A/C REFRIGE | X | | | 1.00 | 758.00 | 23.00 | 583.66 |
| M | PANEL, AIR GUIDE | X | | | 1.00 | 112.00 | 23.00 | 86.24 |
| M | RADIATOR ASSY | X | | | 1.00 | 967.00 | 23.00 | 744.59 |
| M | TANK ASSY, RADIATOR COND | X | | | 1.00 | 42.00 | 23.00 | 32.34 |
| M | FAN, COOLING, LH | X | | | 1.00 | 77.00 | 23.00 | 59.29 |
| M | SHROUD, COOLING FAN | X | | | 1.00 | 130.00 | 23.00 | 100.10 |
| M | MOTOR, COOLING FAN | X | | | 1.00 | 479.00 | 23.00 | 368.83 |
| M | LLC 4L | X | | | 1.00 | 26.00 | 23.00 | 20.02 |
| M | HEADLAMP ASSY, LH | OR | | | 1.00 | 660.00 | 23.00 | 508.20 |
| M | HEADLAMP ASSY, RH | OR | | | 1.00 | 660.00 | 23.00 | 508.20 |
| M | LAMP ASSY, FOG, FR LH | CUT | | | 1.00 | 303.00 | 23.00 | 233.31 |
| M | BOX ASSY, RELAY | OR | | | 1.00 | 139.00 | 23.00 | 107.03 |
| M | COVER, RELAY BOX | CUT | | | 1.00 | 64.00 | 23.00 | 49.28 |
| M | INSULATOR, ENG MOUNTING | 1 | | | 1.00 | 203.00 | 23.00 | 156.31 |
| M | INSULATOR, T/M MOUNTING | 1 | | | 1.00 | 209.00 | 23.00 | 160.93 |
| M | ROD ASSY, ENG ROLL STOPPER | 1 | | | 1.00 | 155.00 | 23.00 | 119.35 |
| M | CROSSMEMBER, FR AXLE, NO.1 | 1 | | | 1.00 | 864.00 | 23.00 | 665.28 |
| M | ARM ASSY, FR SUSP, LWR LH | 1 | | | 1.00 | 337.00 | 23.00 | 259.49 |
| M | STRUT, FR SUSP | 1 | | | 1.00 | 452.00 | 23.00 | 348.04 |
| M | DAMPER, FR SUSP STRUT | 1 | | | 1.00 | 24.00 | 23.00 | 18.48 |
| M | PAD, FR SUSP SPRING | 1 | | | 1.00 | 17.00 | 23.00 | 13.09 |
| M | SEAT, FR SUSP SPRING, UPR | 1 | | | 1.00 | 37.00 | 23.00 | 28.49 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or by bank transfer. We also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|--------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 | Cust No/Name /TAN YONG JIAN (CHEN YONGJIAN) Reg No/Reg Date SMF5857B / 19/11/201 Date In/Mileage / 13102 Chassis No MMBSTA13AJH004336 Engine No 3A92UHK0571 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|------------|--------|-------------------|-----|---------------|--------|
| KAX00008 | Credit | 25/09/2020/ 15:50 | QUD | 247 / DonBong | 57779 |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---------------------------------|------|------------|-------|---------|
| M BEARING,FR SUSP STRUT ? | 1.00 | 9.00 | 23.00 | 6.93 |
| M SUPPORT,FR SUSP STRUT ? | 1.00 | 17.00 | 23.00 | 13.09 |
| M INSULATOR,FR SUSP STRUT ? | 1.00 | 83.00 | 23.00 | 63.91 |
| M INSULATOR,FR SUSP STRUT ? | 1.00 | 98.00 | 23.00 | 75.46 |
| M NUT,CYLINDER BLOCK ? | 1.00 | 3.00 | 23.00 | 2.31 |
| M STOPPER,FR SUSP STRUT ? | 1.00 | 27.00 | 23.00 | 20.79 |
| M KNUCKLE,LH ? | 1.00 | 365.00 | 23.00 | 281.05 |
| M COVER,FR BRAKE DISC ? | 1.00 | 26.00 | 23.00 | 20.02 |
| M BEARING,FR WHEEL HUB ? | 1.00 | 121.00 | 23.00 | 93.17 |
| M SNAP RING,FR WHEEL HUB ? | 1.00 | 8.00 | 23.00 | 6.16 |
| M HUB ASSY,FR WHEEL ? | 1.00 | 215.00 | 23.00 | 165.55 |
| M GEAR & LINK ASSY,STEERING ? | 1.00 | 1444.00 | 23.00 | 1111.88 |
| M END ASSY,TIE ROD ? | 1.00 | 52.00 | 23.00 | 40.04 |
| M END ASSY,TIE ROD ? | 1.00 | 52.00 | 23.00 | 40.04 |
| M WHEEL,DISC / C41 (F4 L4) | 1.00 | 687.00 | 23.00 | 528.99 |
| M SENSOR,FR ABS / TAN | 1.00 | 171.00 | 23.00 | 131.67 |

SURVEYOR NAME: Steve (LKE) 8322 8813

SURVEYOR SIGNATURE: _____

DATE: 28/9/20, 12:00 pmREMARKS: P/P, Recy Before spray

OO - Not Authorize
 EXCER - ?

Conditions accepted by
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Authorized signatory and company stamp
- Supplementary terms: must be resurveyed and

is subject to final approval from Insurance Company
 Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include
 Any additional Repairs or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered
 after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a
 deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or
 cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing
 the rubber seal or other repair requiring the removal of the windscreen.

| | | |
|----------------------|----------|------------------|
| | Nett | 26,430.69 |
| 7% GST on | 26430.69 | 1850.15 |
| Total Payable | | 28,280.84 |