



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NTUC INCOME INSURANCE CO-OPERATIVE LTD C/O: LOW YEAP TOH & GOON 10 ANSON ROAD #18-13 INTERNATIONAL PLAZA SINGAPORE 079903			Ref: CS/LAW20010317/R1qf3e2 Date: 22/02/2021	Code: INC3
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SJB 5857H	Veh. Inspected	GBF 7006H	
Policy No.		Coverage (\$)	0.00	
Claim No.	GEP.2334.05.20.ct	Excess (\$)	0.00	
Assign From	SITI MARINA	Assign Date	25/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA 150 M	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTFAT35Y20K207321	Colour	WHITE	
Odometer	237463 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	GREEN MAX	7 mm	
L/H Front Tyre	195 R15C	GREEN MAX	7 mm	
R/H Rear Tyre	155 R12C (D)	GREEN MAX	5/5 mm	
L/H Rear Tyre	155 R12C (D)	GREEN MAX	5/5 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	05/10/2017	Inspection Date	09/12/2020	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	