



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III18009383/Uqd3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 01-10-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 2556Z	Veh. Inspected	SJQ 622Y
Policy No.	M493726	Coverage (\$)	0.00
Claim No.	MC2018/2443	Excess (\$)	0.00
Assign From	CARINE KHEK	Assign Date	25/09/2020

2. Vehicle Particulars & Condition

Make & Model	SUZUKI SX4 (A)	c.c	1586
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JSAGYA21S00205619	Colour	GREY
Odometer	265690	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	TOYO	6 mm
L/H Front Tyre	205/60 R16	TOYO	6 mm
R/H Rear Tyre	205/60 R16	TOYO	6 mm
L/H Rear Tyre	205/60 R16	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/05/2018	Inspection Date	24/05/2018
Survey held at	TEK SOON MOTOR REPAIR & SPRAY PAINTING AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 BLK D #01-93 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------