

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : IMRAN BIN ABDUL RAHMAN
BLK 356 YISHUN RING ROAD
#05-1814
SINGAPORE 760356

Estimate No: MC1901437
Date: 25 Sep 2020
Policy No: GA452445
Veh Reg No: SMJ6838D
Make/Model: HONDA VEZEL 1.5X
CVT

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 24/09/2020
TP Veh Reg No: SME5272T

Estimate Repair Cost to Vehicle No :SMJ6838D

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 REAR WINDSCREEN MOULDING TOP,SIDE LH & RH & LOWER / BL.	1 PC	120.00	
2 TAILGATE / BL	1 PC	1,050.00	
3 TAILGATE EMBLEM X NN	1 PC	15.70	
4 TAILGATE INNER LOCK ?	1 PC	157.10	
5 TAILGATE RUBBER ?	1 PC	92.30	
6 TAILGATE INNER TRIMBOARD X NN	1 PC	153.40	
7 REAR BUMPER / BL	1 PC	508.50	
8 REAR BUMPER SIDE RETAINERS LH & RH X NN	2 PC	35.00	
9 REAR BUMPER CLIPS / BL	10 PC	35.00	
10 REAR BUMPER REFLECTOR LH & RH ?	2 PC	282.00	
11 END PANEL X Repair.	1 PC	411.90	
12 END PANEL TOP GARNISH X NN	1 PC	92.30	
		2,953.20	
	Less 20%	590.64	2,362.56
Special Nett			
13 REVERSE SENSOR ?	2 PC	200.00	
14 INNER SEAL / BL	1 PC	20.00	
15 SEALANT / BL	1 PC	40.00	
16 REAR BUMPER LOWER SPOILER -CHECK PRICE / Cut.	1 PC	0.0000	
		260.00	260.00
LABOUR			
17 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00 X NN	
18 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00 /	
19 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00 40.	
20 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00 X	
21 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR END PANEL, SPARE TYRE PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00 400.	
22 TO SPRAY TAILGATE, REAR BUMPER, END PANEL, SPARE TYRE PANEL	1 PC	800.00 300.	
		1,880.00	1,880.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : IMRAN BIN ABDUL RAHMAN
BLK 356 YISHUN RING ROAD
#05-1814
SINGAPORE 760356

ATTN:

Estimate No: MC1901437
Date: 25 Sep 2020
Policy No: GA452445
Veh Reg No: SMJ6838D
Make/Model: HONDA VEZEL 1.5X
CVT

Your Ref No: -
Claim Type: Third Party
Accident Date: 24/09/2020
TP Veh Reg No: SME5272T

Estimate Repair Cost to Vehicle No :SMJ6838D

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 4,502.56
		Add GST @ 7%	315.18
		Total Amount Payable	S\$ 4,817.74

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND EIGHT HUNDRED SEVENTEEN AND CENTS SEVENTY FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

4 Days.

P/P.

before paint photos.

Gua Rianp - 82880282

29/9/2020.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: