

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0693/2020/KS  
DATE : 25-Sep-20  
WIP : 50757

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120

*Hi Adrian,  
7 days - ok - Jy - 25 Sep 20*

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT  
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR TEO GUAT THOE  
ADDRESS : 6 MOUNT SINAI LANE  
SINGAPORE 276997  
TELEPHONE : HP +65 96751815  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1900150922  
VEHICLE NO : SKA 8208 E  
MODEL CODE : AUDI Q5 SPORT 2.0 TFSI QU  
MODEL YEAR : 30/08/2019  
ENGINE NO : DAX 058529  
CHASSIS NO : WAUZZZFY1K2125852  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 23-Sep-20  
PLACE OF ACCIDENT : COMMONWEALTH ROAD



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKA 8208 E.**

<b>S/N</b>	<b>NATURE OF JOBS</b>		<b>ESTIMATED CHARGES</b>	<b>SURVEYOR'S RECOMMENDATIONS</b>
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N	\$ 560.00	\$ 280.00
2	TO INSTALL SOLAR FILM FOR LHS FRONT DOOR WINDOW GLASS.	S/N	\$ 400.00	\$ 400.00
3	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 2,800.00	\$ 1,000.00
4	TO RESPRAY LHS FRONT DOOR,LHS WING MIRROR COVER, LHS REAR DOOR, DOOR COVERS, DOOR HANDLES,LHS REAR FENDER AND LHS REAR WHEEL ARCH TRIM		\$ 4,600.00	\$ 2,350.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	\$ 192.00
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 8,552.00</b>	<b>\$ 4,222.00</b>



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKA 8208 E.**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT DOOR LH		\$ 3,118.00	
2	FRONT DOOR OUTER LH		\$ 203.00	
3	BONDING AGENT		\$ 47.00	
4	CLEANING SOLUTION		\$ 65.00	
5	APPLICATOR		\$ 7.00	
6	FRONT DOOR CATCH LH		\$ 144.00	
7	FRONT WING MIRROR MOUNT LH		\$ 1,730.00	\$ 1,384.00
8	FRONT WING MIRROR CAP LH		\$ 467.00	
9	FRONT WING MIRROR GLASS LH		\$ 1,606.00	\$ 1,284.80
10	FRONT DOOR COVER LH		\$ 781.00	
11	FRONT WINDOW SLOT SEAL LH		\$ 609.00	\$ 486.80
12	FRONT DOOR WINDOW LH		\$ 295.00	\$ 235.60
13	REAR DOOR LH		\$ 3,118.00	\$ 2,494.40
14	REAR DOOR OUTER SEAL LH		\$ 203.00	\$ 162.00
15	BONDING AGENT		\$ 47.00	
16	CLEANING SOLUTION		\$ 65.00	
17	APPLICATOR		\$ 7.00	
18	REAR DOOR SEALING STRIP		\$ 16.00	
19	REAR DOOR ATTACHMENT PARTS		\$ 219.00	
20	REAR DOOR CATCH LH		\$ 144.00	\$ 114.80
	<b>SUB-TOTAL SPARE PARTS</b>	<b>:</b>	<b>\$ 12,891.00</b>	<b>\$ 6,162.40</b>

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

