

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

23-Sep-20

## ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1547 S

2 pcs	n/s & o/s reflector @\$295.10	\$	590.20	X un
1 pc	Tailgate	\$	2,292.30	R7
1 pc	Tailgate lower garnish	\$	362.61	Cng
1 pc	Tailgate weatherstrip	\$	276.98	X
1 pc	Tailgate lock	\$	216.48	X
2 pcs	Rear license plate lamp @ \$18.60	\$	37.20	X
1 pc	End panel top garnish	\$	90.00	X
1 pc	Emblem I30	\$	27.80	ner
1 pc	Emblem CRDI	\$	29.40	ner
1 pc	Emblem Hyundai	\$	29.40	ner
1 pc	Rear bumper	\$	811.11	de
1 pc	Rear bumper sponge	\$	79.20	X
1 pc	Rear bumper reinforcement	\$	815.64	X
1 pc	Rear bumper reinforcement centre	\$	79.20	X
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40	X
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	\$	215.00	X
		\$	6,056.92	126032
		\$	2,119.92	1008.25
		\$	3,937.00	

20%  
Less 35%

### S/NETT

1 set	Rear bumper clips	\$	48.00	30 ner
1 set	Reverse sensor	\$	280.00	200 ner
1 set	Tailgate stickers	\$	100.00	ner
1 set	Tailgate lower garnish clips	\$	38.00	20 ner
1 set	End panel inner garnish clips	\$	38.00	X
1 pc	Rear number plate	\$	50.00	X
1 set	Sealant	\$	50.00	X
1 pc	Rear bumper top protector	\$	80.00	X

350.

23-Sep-20

**ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1547 S**

Sundry	\$ 50.00	20 net
Towing Fee	\$ 50.00	X
To dismantle / refit rear windscreen glass onto new tailgate	\$ 120.00	X } un
To dismantle and refit the inner components of wiper onto new tailgate, test wiper motor and water etc	\$ 120.00	X }
To dismantle and replace reverse sensor and test system	\$ 80.00	30
To labour charge for dismantle and renewal of the accident damaged parts. To heat/weld & cut end panel. Including knock-out, straighten, repair, reshape of the same	\$ 1,000.00	400
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, tailgate, end panel,	\$ 800.00	500
To apply rustproofing on the repaired and replaced panels	\$ 150.00	X 20
<b>Total</b>	<b>\$ 6,991.00</b>	<b>950</b>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

Taufik 97495749  
- WP' 28/9/20 @ 3pm  
1/5 Resurvey after repair  
0.3 days  
Taufik @ 11:00pm

1008.25  
350  
950  
2308.25  
1/5 \$1800, 0.3 day 3#

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date: