

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

23-Sep-20

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1547 S

2 pcs	n/s & o/s reflector @\$295.10	\$	590.20 X
1 pc	Tailgate	\$	2,292.30 RT
1 pc	Tailgate lower garnish	\$	362.61 CNA /
1 pc	Tailgate weatherstrip	\$	276.98 X
1 pc	Tailgate lock	\$	216.48X
2 pcs	Rear license plate lamp @ \$18.60	\$	37.20X
1 pc	End panel top garnish	\$	90.00X
1 pc	Emblem I30	\$	27.80 ne /
1 pc	Emblem CRDI	\$	29.40 ne /
1 pc	Emblem Hyundai	\$	29.40 ne /
1 pc	Rear bumper	\$	811.11 de /
1 pc	Rear bumper sponge	\$	79.20 ?
1 pc	Rear bumper reinforcement	\$	815.64 .
1 pc	Rear bumper reinforcement centre	\$	79.20 ?
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40 X
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	\$	215.00 X
		\$	6,056.92
		Less 35%	\$ 2,119.92
		\$	3,937.00

S/NETT

1 set	Rear bumper clips	\$	48.00 30 ne /
1 set	Reverse sensor	\$	280.00 200 ne /
1 set	Tailgate stickers	\$	100.00 ne /
1 set	Tailgate lower garnish clips	\$	38.00 20 ne /
1 set	End panel inner garnish clips	\$	38.00 X
1 pc	Rear number plate	\$	50.00 X
1 set	Sealant	\$	50.00 X
1 pc	Rear bumper top protector	\$	80.00 X

23-Sep-20

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1547 S

Sundry	\$ 50.00	20 net /
Towing Fee	\$ 50.00	X
To dismantle / refit rear windscreen glass onto new tailgate	\$ 120.00	X
To dismantle and refit the inner components of wiper onto new tailgate, test wiper motor and water etc	\$ 120.00	X
To dismantle and replace reverse sensor and test system	\$ 80.00	30
To labour charge for dismantle and renewal of the accident damaged parts. To heat/weld & cut end panel. Including knock-out, straighten, repair, reshape of the same	\$ 1,000.00	400
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, tailgate, end panel,	\$ 800.00	500
To apply rustproofing on the repaired and replaced panels	\$ 150.00	X
Total	\$ 6,991.00	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Taufik 97495747
- WP' 28/9/20 @ 3pm
4/5 Resurvey after repair
3 days
Taufik @ 11h30pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: