

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

25/09/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Alh
Khanchana.

Accident date: 25/09/2020

Estimated repair cost for vehicle no: SJP8156D HONDA FIT 1.3G SKYROOF A 09'

CHASSIS: GE61111543

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dislo Aed</i>		\$820.30 ✓
2	2	Rear Boot Lid Hinge <i>new</i>	\$48.90	\$97.80 ✓
3	2	Rear Boot Lid Shock Absorber <i>new</i>	\$184.90	\$369.80 ✓
4	1	Rear Boot Lid Emblem Logo <i>new</i>		\$38.10 ✓
6	1	Rear Boot Lid Number Plate <i>new</i>		\$50.00 ✓
7	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$48.20	\$96.40 ✓
8	1	Rear Boot Lid Centre Moulding <i>cracked</i>		\$120.60 ✓
9	6	Rear Boot Lid Centre Moulding Clip <i>new</i>	\$6.50	\$39.00 ✓
10	1	Rear Boot Lid Inner Lock <i>damaged</i>		\$232.10 ✓
11	1	Rear Boot Lid Inner Rubber <i>lt</i>		\$128.10 ✓
12	1	Rear Boot Lid Inner Trim Board <i>cracked</i>		\$296.70 ✓
13	1	Rear Boot Lid Wiper Link <i>new</i>		\$175.90 ✓
14	1	Rear Boot Lid Wiper Cover <i>new</i>		\$45.00 ✓
15	1	Rear Boot Lid Wiper Arm <i>new</i>		\$86.00 ✓
16	1	Rear Boot Lid Wiper Motor <i>new</i>		\$328.50 ✓
17	1	Rear Boot Lid Windscreen <i>new</i>		\$1,256.20 ✓
18	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$136.20 ✓
19	2	Rear Tail Lamp <i>cracked</i>	\$296.50	\$593.00 ✓
20	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 ✓
21	2	Rear Tail Lamp Panel <i>cracked</i>	\$191.70	\$383.40 ✓
22	2	Rear Tail Lamp Inner Panel <i>new</i>	\$482.30	\$964.60 ✓
23	1	Rear Bumper <i>Distorted</i>		\$494.60 ✓
24	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 ✓
25	2	Rear Bumper Side Retainer <i>new</i>	\$28.70	\$57.40 ✓
26	1	Rear Bumper Towing Cover <i>Delaid</i>		\$28.00 ✓
27	2	Rear Bumper Mud Shield <i>RH torn</i>	\$94.80	\$189.60 ✓
28	8	Rear Bumper Mud Shield Clip <i>new</i>	\$6.50	\$52.00 ✓

94.80

10

29	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$350.00	<i>2w/sn</i>
30	1	Rear End Panel <i>Distorted</i>		\$365.30	✓
31	1	Rear End Panel Top Garnish <i>Cracked</i>		\$140.20	✓
32	2	Rear Fender <i>Reps</i>	\$682.20	\$1,364.40	✓
34	2	Rear Fender Air Duct <i>NEW</i>	\$38.00	\$76.00	✗
35	2	Rear Fender Inner Panel <i>Reps</i>	\$633.00	\$1,266.00	✗
36	2	Rear Fender Inner Housing <i>Reps</i>	\$596.40	\$1,192.80	✗
37	2	Rear Fender Top Trim Board <i>Cracked</i>	\$293.60	\$587.20	<i>405</i>
38	2	Rear Fender Inner Trim Board <i>Del</i>	\$339.80	\$679.60	<i>490</i>
39	16	Rear Fender Inner Trim Board Clip <i>NEW</i>	\$6.50	\$104.00	<i>60</i>
40	1	Rear Spare Tyre Panel <i>Bruckend</i>		\$737.40	✓
41	1	Rear Spare Tyre Panel Top Cover <i>Del</i>		\$260.40	✓
42	1	Rear Spare Tyre Panel Top Sponge <i>Cracked</i>		\$206.00	✓
43	1	Rear Spare Tyre Panel Sealant <i>NEW</i>		\$450.00	✗
44	2	Rear Spare Tyre Side Panel <i>Reps</i>	\$151.20	\$302.40	✗
46	1	Rear Exhaust <i>Best Best</i>		\$2,800.00	<i>700 (sn)</i>
49	2	Rear Exhaust Mounting <i>NEW</i>	\$90.00	\$180.00	✗

Subtotal :- \$18,225.00

6179.60

S.N: 900

4943.68

Labour charges

To remove & refit cushion & trim board	\$280.00 120
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To remove & refit rear LH & RH fender glass	\$200.00 x
Gum	\$100.00 +
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & centre exhaust	\$380.00 80
To check wiring	\$120.00 30
Towing fee	\$150.00 x
Tuff kote	3370 \$150.00 120
Panel beating	\$3,500.00 1400
Spray painting	\$2,800.00 1400

Subtotal :- \$7,950.00

Total:- \$26,175.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian C
L/S 28/09/20

11 Days.

Supplementary: 830

total: 10043.68
L/S: 8/K

(8/K)

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

28/09/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 25/09/2020

Supplementary repair cost for vehicle no: SJP8156D HONDA FIT 1.3G SKYROOF A 09'

CHASSIS: GE61111543

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Sound Proof Insulation Liner <i>me</i>		\$750.00 250 (SN)
2	1	Rear Boot Lid Inner Trimboard Sound Proof Liner <i>me</i>		\$350.00 180 (SN)
3	2	Rear Fender Top Inner Trimboard <i>reported</i>	\$221.20	\$442.40 +
4	1	Rear Windscreen <i>item</i>		\$1,256.20 +
5	1	Rear Windscreen Seal <i>me</i>		\$136.20 +
6	1	Rear Camera. Danged	580. 400 (SN)	
Subtotal :-				\$2,934.80

Admin L
28/09/20.

Supplementary : 830