

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Muhammad Sulhilmi Bin Najib

Accident Date : 23-Sep-20

Vehicle No : FBJ5783P

Vehicle Model : Yamaha  
Jupiter MX(HC)

## Estimated Repair Costs

| Qty        | Description                  | Amount S(\$)                              |
|------------|------------------------------|-------------------------------------------|
| List Items |                              |                                           |
| 1          | Front fork tube assy         | \$ <del>240</del> <sup>TWI</sup> 640.00 ✓ |
| 1          | Front wheel rim              | \$ <del>280</del> 280.00 X                |
| 1          | Fork under bracket           | \$ <del>185</del> 185.00 ✓                |
| 1          | Front rim shaft              | \$ <del>45</del> 45.00 X                  |
| 1          | Front rim bearing            | \$ <del>38</del> 38.00 ✓                  |
| 1          | Front brake disc             | \$ <del>155</del> 155.00 ✓                |
| 1          | Handle-bar                   | \$ <del>105</del> 105.00 X                |
| 1          | Handle-bar end (1 set) 60.00 | \$ <del>100</del> 100.00 ✓                |
| 1          | Handle-bar bracket           | \$ <del>95</del> 95.00 X                  |
| 1          | Hand grip (1 set)            | \$ <del>55</del> 55.00 ✓                  |
| 2          | Side mirrors - R/L 55.00     | n/s \$ <del>110</del> 110.00 ✓            |
| 1          | Clutch lever                 | \$ <del>30</del> 30.00 ✓                  |
| 1          | Headlamp                     | \$ <del>200</del> 200.00 ✓                |
| 1          | Fairing assy (1 set)         | \$ <del>535</del> 535.00 ✓                |
| 1          | Centre inner panel 115.00    | \$ <del>145</del> 145.00 ✓                |
| 1          | Front footrest brackets      | \$ <del>65</del> 65.00 ✓                  |
| 1          | Front footrest rubber - L/H  | \$ <del>35</del> 35.00 ✓                  |
| 1          | Gear pedal                   | \$ <del>42</del> 42.00 X                  |
| 1          | Rear footrest - L/H          | \$ <del>40</del> 40.00 ✓                  |
| 1          | Rear footrest bracket - L/H  | \$ <del>78</del> 78.00 ✓                  |
| 1          | Side stand                   | \$ <del>75</del> 75.00 X                  |
| 1          | Main stand                   | \$ <del>95</del> 95.00 X                  |
| 1          | Basket                       | \$ <del>80</del> 80.00 X                  |
|            |                              | \$ 3,228.00                               |
| Less 10%   |                              | \$ 322.80                                 |
|            |                              | \$ 2,905.20                               |

not Authored  
Lm  
2/8 \$2200  
4 days

Whepbe Atkin  
28/9/20

2098  
102  
1888.20

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Muhammad Sulhilmi Bin Najib

Accident Date : 23-Sep-20

Vehicle No : FBJ5783P

Vehicle Model : Yamaha  
Jupiter MX(HC)

## Estimated Repair Costs

### Special Nett Items

|   |                       |                  |
|---|-----------------------|------------------|
| 1 | Number plate (1 set)  | for \$ 28.00 10  |
| 2 | Fork oils             | \$ 11 30.00 X    |
| 2 | Fork oil seals        | \$ 11 56.00 X    |
| 1 | Steering cone (1 set) | \$ 11 95.00 ✓    |
| 1 | Sticket (1 set)       | \$ 11 95.00 —    |
| 1 | Rear box              | \$ 11 180.00 —   |
| 1 | Rear box bracket      | \$ 11 140.00 X   |
| 1 | E.R.P. IU unit        | CU \$ 200.00 175 |
|   |                       | \$ 824.00        |

### S/No.

### Labour

|   |                                             |                |
|---|---------------------------------------------|----------------|
| 1 | To provide towing service                   | \$ 50.00 ✓     |
| 2 | To check wiring and reset headlamp focusing | \$ 11 80.00 X  |
| 3 | To repair body alignment                    | \$ 11 380.00 X |
| 4 | To provide labour                           | \$ 280 450.00  |
|   |                                             | \$ 960.00      |

### Grand Total

\$ 4,689.20

Dollars: Four Thousand Six Hundred Eighty-Nine and Cents: Twenty only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

P-1888.20  
S.W. 558.00  
L-330.00  
2773.20  
202  
2218.