

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Sep 2020		29 Sep 2020 15:40 Edit Adj Rpt	S\$2,200.00 Edit Estimates	S\$2,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	-, Co. Reg. No.: -								
Main Claimant:	MUHAMMAD ZULHILMI BIN NAJIB								
Vehicle Reg. No.:	FBJ5783P	Date of Loss:	23/09/2020 17:00 - :59 [74 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D203515C02	Policy/Cover Note No.:	DMCVSN30461619055						
Vehicle Reg. No. (Insured):	GP9690C	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62, 417883 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/10/2020]								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBJ5783P (SNM20D203515C02)
[GP9690C]
TP
MUHAMMAD ZULHILMI BIN NAJIB
Sep 23 2020 5:00PM
[-]
Erofia Motor Trading Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser ▼

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/09/20 15:51	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/09/20 15:21	Odometer Reading	 Load JPG	☒
2	30/09/20 15:23	General View	 Load JPG	☒
3	30/09/20 15:23	General View	 Load JPG	☒
4	30/09/20 15:23	General View	 Load JPG	☒
5	30/09/20 15:23	General View	 Load JPG	☒
6	30/09/20 15:23	General View	 Load JPG	☒
7	30/09/20 15:23	General View	 Load JPG	☒
8	30/09/20 15:23	General View	 Load JPG	☒
9	30/09/20 15:23	General View	 Load JPG	☒
10	30/09/20 15:23	General View	 Load JPG	☒
11	30/09/20 15:23	General View	 Load JPG	☒
12	30/09/20 15:23	General View	 Load JPG	☒
13	30/09/20 15:23	General View	 Load JPG	☒
14	30/09/20 15:23	General View	 Load JPG	☒
15	30/09/20 15:23	General View	 Load JPG	☒
16	30/09/20 15:23	General View	 Load JPG	☒
17	30/09/20 15:23	General View	 Load JPG	☒
18	30/09/20 15:23	General View	 Load JPG	☒
19	30/09/20 15:24	General View	 Load JPG	☒
20	30/09/20 15:24	General View	 Load JPG	☒
21	30/09/20 15:24	General View	 Load JPG	☒
22	30/09/20 15:24	General View	 Load JPG	☒
23	30/09/20 15:24	General View	 Load JPG	☒
24	30/09/20 15:24	General View	 Load JPG	☒
25	30/09/20 15:24	General View	 Load JPG	☒
26	30/09/20 15:24	General View	 Load JPG	☒
27	30/09/20 15:24	General View	 Load JPG	☒
28	30/09/20 15:24	General View	 Load JPG	☒
29	30/09/20 15:24	General View	 Load JPG	☒
30	30/09/20 15:24	General View	 Load JPG	☒
31	30/09/20 15:24	General View	 Load JPG	☒
32	30/09/20 15:24	General View	 Load JPG	☒
33	30/09/20 15:24	General View	 Load JPG	☒
34	30/09/20 15:24	General View	 Load JPG	☒
35	30/09/20 15:24	General View	 Load JPG	☒
36	30/09/20 15:24	General View	 Load JPG	☒
37	30/09/20 15:24	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	30/09/20 15:24	General View	 Load JPG	☒
39	30/09/20 15:24	General View	 Load JPG	☒
40	30/09/20 15:24	General View	 Load JPG	☒
41	30/09/20 15:24	General View	 Load JPG	☒
42	30/09/20 15:24	General View	 Load JPG	☒
43	30/09/20 15:24	General View	 Load JPG	☒
44	30/09/20 15:24	General View	 Load JPG	☒
45	30/09/20 15:24	General View	 Load JPG	☒
46	30/09/20 15:24	General View	 Load JPG	☒
47	30/09/20 15:24	General View	 Load JPG	☒
48	30/09/20 15:24	General View	 Load JPG	☒
49	30/09/20 15:24	General View	 Load JPG	☒
50	30/09/20 15:24	General View	 Load JPG	☒
51	30/09/20 15:24	General View	 Load JPG	☒
52	30/09/20 15:24	General View	 Load JPG	☒
53	30/09/20 15:24	General View	 Load JPG	☒
54	30/09/20 15:24	General View	 Load JPG	☒
55	30/09/20 15:24	General View	 Load JPG	☒
56	30/09/20 15:24	General View	 Load JPG	☒
57	30/09/20 15:24	General View	 Load JPG	☒
58	30/09/20 15:24	General View	 Load JPG	☒
59	02/10/20 07:52	Chassis Number	 Load JPG	☒
60	02/10/20 07:52	Reinspection Photo	 Load JPG	☒
61	02/10/20 07:52	Reinspection Photo	 Load JPG	☒
62	02/10/20 07:52	Reinspection Photo	 Load JPG	☒
63	02/10/20 07:52	Reinspection Photo	 Load JPG	☒
64	02/10/20 07:52	Reinspection Photo	 Load JPG	☒
65	02/10/20 07:52	Reinspection Photo	 Load JPG	☒
66	02/10/20 07:52	Reinspection Photo	 Load JPG	☒
67	02/10/20 07:52	Reinspection Photo	 Load JPG	☒
68	02/10/20 07:52	Reinspection Photo	 Load JPG	☒
69	02/10/20 07:52	Reinspection Photo	 Load JPG	☒
70	02/10/20 07:52	Reinspection Photo	 Load JPG	☒
71	02/10/20 07:52	Reinspection Photo	 Load JPG	☒
72	02/10/20 07:52	After Repair Photo	 Load JPG	☒
73	02/10/20 07:52	After Repair Photo	 Load JPG	☒
74	02/10/20 07:52	After Repair Photo	 Load JPG	☒
75	02/10/20 07:52	After Repair Photo	 Load JPG	☒
76	02/10/20 07:52	After Repair Photo	 Load JPG	☒
77	02/10/20 07:52	After Repair Photo	 Load JPG	☒
78	02/10/20 07:52	After Repair Photo	 Load JPG	☒
79	02/10/20 07:52	After Repair Photo	 Load JPG	☒
80	02/10/20 07:52	After Repair Photo	 Load JPG	☒
81	02/10/20 07:52	After Repair Photo	 Load JPG	☒
82	02/10/20 07:52	After Repair Photo	 Load JPG	☒
83	02/10/20 07:52	After Repair Photo	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20010342/USD3S2**Date:** 07/10/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30461619055
Claimant Vehicle No :	FBJ5783P	Insured Vehicle No :	GP9690C
Date of Loss:	23/09/2020	Nature of Claim:	TP
		Claim No:	SNM20D203515C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBJ5783P	Engine No:	50C683045
Make & Model:	YAMAHA JUPITER MX, 134cc HC	Chassis No:	MH350C004DK682886
Reg. Date:	21/07/2014 (Man. Year: 2013)	Odometer:	46794 km
Colour:	Red/Black		
Engine Capacity:	134 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	80-90-17	Rear Tyre Size:	90-80-17
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,729.20	2,443.20	1,286.00	34.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	330.00	630.00	65.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,689.20	2,773.20	1,916.00	40.86
Approved Total (Overridden) (\$\$)		2,200.00		
Nett Amount (\$\$)	4,689.20	2,200.00	2,489.20	53.08

INSPECTION

Date of Assignment:	29/09/2020	
Date Inspected:	28/09/2020	Inspected At: Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Oct 2020)	
Parts:	N/A	YAMAHA JUPITER MX 134cc HC (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBJ5783P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK TUBE ASSY	Bent / Twisted	640.00 FL	*640.00 FL
2	1		*FRONT WHEEL RIM	Repair	280.00 FL	*- FL
3	1		*FORK UNDER BRACKET	Bent	185.00 FL	*185.00 FL
4	1		*FRONT RIM SHAFT	Bent	45.00 FL	*45.00 FL
5	1		*FRONT RIM BEARING	Necessary	38.00 FL	*38.00 FL
6	1		*FRONT BRAKE DISC	Not Necessary	155.00 FL	*- FL
7	1		*HANDLE-BAR	Serviceable	105.00 FL	*- FL
8	1		*SET HANDLE-BAR END	Scratched	100.00 FL	*60.00 FL
9	1		*HANDLE-BAR BRACKET	Not Necessary	95.00 FL	*- FL
10	1		*SET HAND GRIP	Cut	55.00 FL	*55.00 FL
11	1		*SIDE MIRRORS - R/L	N/s Cut	110.00 FL	*55.00 FL
12	1		*CLUTCH LEVER	Scratched	30.00 FL	*30.00 FL
13	1		*HEADLAMP	Cut	200.00 FL	*200.00 FL
14	1		*SET FAIRING ASSY	Cut	535.00 FL	*535.00 FL
15	1		*CENTRE INNER PANEL	Cracked	145.00 FL	*115.00 FL
16	1		*FRONT FOOTREST BRACKETS	Bent	65.00 FL	*65.00 FL
17	1		*FRONT FOOTREST RUBBER - L/H	Torn	35.00 FL	*35.00 FL
18	1		*GEAR PEDAL	Serviceable	42.00 FL	*- FL
19	1		*REAR FOOTREST - L/H	Cut	40.00 FL	*40.00 FL
20	1		*REAR FOOTREST BRACKET - L/H	Not Necessary	78.00 FL	*- FL
21	1		*SIDE STAND	Not Necessary	75.00 FL	*- FL
22	1		*MAIN STAND	Not Necessary	95.00 FL	*- FL
23	1		*BASKET	Not Necessary	80.00 FL	*- FL
24	1		*SET NUMBER PLATE (FRONT)	Bent	28.00 FS	*10.00 FS
25	1		*FORK OILS	Not Necessary	30.00 FS	*- FS
26	1		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
27	1		*SET STEERING CONE	Necessary	95.00 FS	*95.00 FS
28	1		*SET STICKER	Necessary	95.00 FS	*95.00 FS
29	1		*REAR BOX	Cut	180.00 FS	*180.00 FS
30	1		*REAR BOX BRACKET	Not Necessary	140.00 FS	*- FS
31	1		*E.R.P. IU UNIT	Cut	200.00 FS	*175.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,052.00	2,653.00
- List Item Discount on L Items 10.00/10.00% (\$)	322.80	209.80
Total Parts (\$)	3,729.20	2,443.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE.	New	50.00	50.00
2	TO CHECK WIRING AND RESET HEADLAMP FORCUSING.	New	80.00	0.00
3	TO REPAIR BODY ALIGNMENT.	New	380.00	0.00
4	TO PROVIDE LABOUR.	New	450.00	280.00
Gross Labour Cost (\$\$)			960.00	330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >