

WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E

Quotation

DATE:

21/09/20

LOCATION:

Gul Workshop

VEHICLE NO:

PD5858Z

Q REF No:

Q20/09/1161

DRIVER:

ZHAO WEI

DEPARTMENT:

ATTENTION TO:

WTS T&T ACCIDENT DATE: 18/09/20

PREPARED BY:

Chan Soo Lye

REF No:

JW-0920-347

S/N	Description	Qty	Cost per Unit	Amount S\$
	Labour Costs			
1	TO REPAIR AND KNOCK RHS REAR MUDGUARD COVER, TO CLEAN RHS REAR TYRE ACCIDENT AREA.	1	400	400.00
	Spray Paint			
1	Spray Painting	1	500	500.00
	TO PUTTY AND SPRAY PAINTING RHS REAR MUDGUARD COVER,			
			TOTAL:	900.00
			Total Amount	SGD 900.00

Remarks:

Signature of Workshop Dpt

Signature of Department Head

Signature of Claim Department