



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GX8368C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE REG. DATE : 2017

ACCIDENT DATE : 18/09/2020

TP VEH REG NO : GX8368C

ESTIMATE

NO : QUOT202009-000072(00)

DATE : 25/09/2020

POLICY NO : 999995580

VEH REG NO : GBG9738K

MAKE/MODEL : MERCEDES BENZ CITAN 109
CDI EL 5MT 6DR

CHASSIS NO : WDF4156052U221537

ENGINE NO : K9KE628D403982

Estimate Repair Cost to Vehicle No : GBG9738K

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Rear wiper cap /scr X SVC	1	28.00	28.00 X
2 Rear door - LH /pb	1	1,575.00	1,575.00 ✓
3 Rear door lock - LH X SVC	1	275.00	275.00 X
4 Rear door inner trimboard - LH X SVC	1	135.00	135.00 X
5 Rear door trimboard clips - LH X SVC	8	5.50	44.00 20SN
6 Rear door centre logo - LH /NEC	1	57.00	57.00 ✓
7 Rear door 'CITAN' emblem - LH /NEC	1	58.00	58.00 ✓
8 Rear door - RH /pb	1	1,080.00	1,080.00 ✓
9 Rear door '109 CDI' emblem - RH /NEC	1	58.00	58.00 ✓
10 Rear door inner trimboard clips - RH X SVC	8	5.50	44.00 20SN
11 Rear door inner reflector - RH X SVC	1	58.00	58.00 X
12 Rear end panel (outer) 2 X SVC	1	715.00	715.00 X
13 Rear bumper X /CR4.	1	1,200.00	1,200.00 ✓
14 Rear bumper reinforcement ? X SVC	1	325.00	325.00 X
15 Rear bumper clips /NEC.	15	9.00	135.00 30SN
			5,787.00 4,028
		Less 10%	578.70 -10%
			5,208.30 3,625.20
SPECIAL NET			
16 Rear door glass sealant - LH /NEC	1	40.00	40.00 ✓
17 Rear door 'C&C' emblem - LH /NEC	1	38.00	38.00 ✓
18 Rear door glass sealant - RH /NEC	1	40.00	40.00 ✓
19 Rear bumper sensor (set) /short	1	280.00	280.00 200
20 Rear door '4 paxs' sticker - LH /NEC	1	25.00	25.00 ✓
21 Rear door '70km/h' sticker - RH /NEC	1	25.00	25.00 ✓
22 Rear number plate /scr	1	40.00	40.00 ✓
			488.00 478
LABOUR			
23 To remove and refix both side rear door glass	1	160.00	160.00 120
24 To transfer damaged both rear door interior mechanism to new door	1	200.00	200.00 120
25 To remove and refix rear bumper sensor	1	80.00	80.00 30
26 To check and rectify wiring system	1	60.00	60.00 30



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GX8368C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE REG. DATE : 2017

ACCIDENT DATE : 18/09/2020

TP VEH REG NO : GX8368C

ESTIMATE

NO : QUOT202009-000072(00)

DATE : 25/09/2020

POLICY NO : 999995580

VEH REG NO : GBG9738K

MAKE/MODEL : MERCEDES BENZ CITAN 109
CDI EL 5MT 6DR

CHASSIS NO : WDF4156052U221537

ENGINE NO : K9KE628D403982

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : GBG9738K

Description	Quantity	Unit Price	Amount
		S\$	S\$
27 To panel beat and straighten rear floorboard panel, rear chassis frame, to cut and weld rear end panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
28 To putty and spray same on affected areas	1	1,200.00	1,200.00
29 To apply rust proofing on repaired and replaced panels	1	80.00	80.00
			2,780.00
		TOTAL	S\$ 8,476.30
		ADD GST @ 7%	593.34
		GRAND TOTAL	S\$ 9,069.64

SINGAPORE DOLLAR NINE THOUSAND SIXTY-NINE AND CENTS SIXTY-FOUR ONLY

Repair days 14 days

4/5

before paint photos

Sun Pin (4th)

28/09/2020

TP with prepa

Sunpin@lkkauto.com

8661 2627

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P = 3,625.20

N = 478

L = 1,450

5,553.20

- 20%

4,442.56

4/5

\$4,450

4 days

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE