

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0701/2020/NS
DATE	:	28-Sep-20
WIP	:	51020

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SLG 1136 G

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MS HONG HUIXIA
ADDRESS	:	30 KOVAN ROAD
		#02-01
		SINGAPORE 329111
TELEPHONE	:	HP +65 88112722
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	1700032198-03
VEHICLE NO	:	SKQ 2722 S
MODEL CODE	:	AUDI A4 SEDAN 1.4 TFSI S TRONIC
MODEL YEAR	:	31/7/2017
ENGINE NO	:	CVN 039088
CHASSIS NO	:	WAUZZZF46HA165534
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	26-Sep-20
PLACE OF ACCIDENT	:	32 KOVAN ROAD S548102(OUTSIDE KOVAN APARTMENT)

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKQ 2722 S**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N	\$ 360.00	✓
2	TO RENEW REAR WINDSCREEN AND RHS REAR 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N	\$ 600.00	X
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND RHS REAR 1/4 GLASS.	S/N	\$ 400.00	X
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS.	S/N	\$ 200.00	X
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N	\$ 1,400.00	X
SUB TOTAL LABOUR CHARGES		:	\$ 2,960.00	

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKQ 2722 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00 ✓	
7	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,000.00 750	
8	TO RESPRAY REAR BUMPER, REAR LID, RHS REAR FENDER, DOOR ENTRANCES, RHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 4,000.00 1100	
9	TO CARRY OUT PRE AND POST WHEEL ALIGNMENT. TO RENEW RHS REAR RIM.	S/N \$ 520.00 260	
10	TO TOW VEHICLE FROM ACCIDENT SCENE	S/N \$ 280.00 X	
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
12	TO RE-APPLY PAINT COATING.	S/N PRICE TBC ?	
TOTAL LABOUR CHARGES		: \$ 13,352.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKQ 2722 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR BUMPER <i>torn</i>		\$	2,181.00	✓
2 REAR BUMPER FIXING PARTS <i>new</i>		\$	72.00	✓
3 REAR BUMPER SECURING STRIP <i>new</i>		\$	220.00	✓
4 REAR BUMPER SPOILER <i>torn</i>		\$	246.00	✓
5 REAR LIGHT REFLECTOR - RH <i>new</i>		\$	41.00	✓
6 LED TAIL LIGHT - RH <i>2 new</i>		\$	1,008.00	✓
7 TAIL LIGHT TRIM - RH <i>new</i>		\$	30.00	✓
8 REAR BUMPER GUIDE SECTION - TH <i>could</i>		\$	45.00	✓
9 REAR BUMPER GUIDE SECTION - LH / RH ?	2	\$	44.00	✓
10 REAR BUMPER CARRIER <i>2 new</i>		\$	886.00	✓
11 REAR BUMPER CARRIER SEAL <i>new</i>	2	\$	28.00	✓
12 REAR PARKING AID SENSOR - INNER / OUTER ?	2		TBC ?	
13 REAR PARKING AID SEAL RING <i>new</i>	4	\$	14.00	✓
14 BOOT LID CONTROL UNIT <i>new</i>		\$	399.00	✓
15 REAR FENDER - RH <i>Repis</i>		\$	2,644.00	✓
16 REAR WINDSCREEN <i>2</i>		\$	1,141.00	✓
17 SIDE WINDOW - RH <i>new</i>		\$	609.00	✓
18 PRIMER <i>new</i>		\$	19.00	✓
19 VENT TRIM <i>could</i>		\$	66.00	✓
20 WHEEL HOUSING LINER - RH <i>torn</i>		\$	237.00	✓
SUB TOTAL SPARE PARTS		:	\$	9,930.00

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKQ 2722 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 WHEEL HOUSING LINER <i>HP</i>		\$	90.00	X
22 AUDI EMBLEM		\$	122.00	X
23 A4 INSCRIPTION		\$	95.00	X
24 TFSI INSCRIPTION <i>HP</i>		\$	95.00	X
25 PACKING ADHESIVE <i>HP</i>		\$	18.00	X
26 REAR NO PLATE	S/N	\$	60.00	X
27 REAR WINDSCREEN SEALANT <i>HP</i>	S/N	\$	200.00	X
28 REAR RIM - RH <i>cut</i>			TBC	✓
29 1/4 GLASS SEALANT	S/N	\$	100.00	X
30 METAL FILLER POWDER	S/N	\$	280.00	✓
31 STONE CHIP <i>HP</i>	S/N	\$	180.00	X
32 CAVITY WAX <i>HP</i>	S/N	\$	140.00	X
33 ACRYLIC SEALANT	S/N	\$	180.00	X
34 SUNDRIES		\$	350.00	?
TOTAL SPARE PARTS	:	\$	11,840.00	
TOTAL LABOUR CHARGES	:	\$	13,352.00	
GRAND TOTAL	:	\$	25,192.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ly*
SURVEYED DATE : *28/09/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 0 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

Operations @SCL Freight Solutions

From: CS-II <unique1995@gmail.com>
Sent: Monday, 28 September 2020, 10:23
To: Jennahong.m@gmail.com
Subject: Re: Quotation of Paint Protection

Hi Jenna,

Thank you for interest in our coating.

The price of Audi A4 as below:

Ceramic Coating (3 Year Warranty)

Price : \$1003

Ceramic is the single layer hard coating, suitable for indoor parking cars, protects from light scratches and color fading, protects from UV rays.

Our process includes free RIM Coating, Clear Vue for all 4 windows and Rear Glass Except for Front Windscreen, leather treatment and interior Vacuum.

What is under warranty period:

- if the Gloss Unit index drops by 10% of the initial measurement, we will recoat the entire car with NO Charge. (we have a device to measure this)
- if the coated car needed to undergo repair and spray painting. Out of well gesture, we can touch up 3 panels with no additional charges however, any additional panel might incur minimum cost. Touch up subject to availability, please call to fix an appointment.

What is not under warranty ?

- Chips off, scratches, watermark, bird dropping and tree sap is not under warranty however, you can bring back and we will try to help to fix as much as possible
 - For maintenance package (Optional):
- A Rejuvenation to make your car looks better
- No extended warranty when doing maintenance

If you have any questions please do not hesitate to let me know, looking forward to hearing from you soon. Thank you.

Best Regards,

Jocelyn



Unique Car Beauty Shop

53, Ubi Ave 1, #01-40, Paya Ubi Industrial Park Singapore 408934
Web: www.cs2singapore.com, Email: info@cs2singapore.com

Bill To	Bill To
Customer: Jenna	Customer: Jenna
Address:	Address:
Telephone: 97562958	Telephone: 97562958

Invoice



Item #	Name / Description	Quantity	Unit Price	Subtotal
1	Ceramic Coating - Executive SKQ2722S (Red Audi A4) - x1	1	1,100.00	\$1,100.00
2	RIM Coating (\$40/rim) SKQ2722S (Red Audi A4) - x4	4	40.00	\$160.00

FOR LEATHER CONDITIONING (UNCLAIMED)
10/08/17

Signature/Stamp / Remarks

Discount:	\$ -435.00
Net Total:	\$925.00
SGD Total:	\$925.00

This is computer generated document no signature required.