

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0701/2020/NS  
**DATE** : 28-Sep-20  
**WIP** : 51020

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.**

**YOUR INSURED VEH NO : SLG 1136 G**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

**Hi Adrian**

**5 days exclude 1 Sunday**

**jb 22 Jan 21**

**ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**

**TEL: 6841 0055 - FAX: 6256 4315**

**OWNER'S NAME** : MS HONG HUIXIA  
**ADDRESS** : 30 KOVAN ROAD  
#02-01  
SINGAPORE 329111  
**TELEPHONE** : HP +65 88112722  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 1700032198-03  
**VEHICLE NO** : **SKQ 2722 S**  
**MODEL CODE** : AUDI A4 SEDAN 1.4 TFSI S TRONIC  
**MODEL YEAR** : 31/7/2017  
**ENGINE NO** : CVN 039088  
**CHASSIS NO** : WAUZZZF46HA165534  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 26-Sep-20  
**PLACE OF ACCIDENT** : 32 KOVAN ROAD S548102(OUTSIDE KOVAN APARTMENT)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKQ 2722 S**

| <b>S/N</b>                      | <b>NATURE OF JOBS</b>                                                                                                          | <b>ESTIMATED CHARGES</b> |                    |
|---------------------------------|--------------------------------------------------------------------------------------------------------------------------------|--------------------------|--------------------|
| 1                               | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.                | S/N                      | \$ 360.00          |
| 2                               | TO RENEW REAR WINDSCREEN AND RHS REAR 1/4 GLASS TO FACILITATE FENDER RENEWAL.                                                  | S/N                      | \$ 600.00          |
| 3                               | TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND RHS REAR 1/4 GLASS.                                                              | S/N                      | \$ 400.00          |
| 4                               | TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS.                                                                                 | S/N                      | \$ 200.00          |
| 5                               | TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. | S/N                      | \$ 1,400.00        |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                                | <b>:</b>                 | <b>\$ 2,960.00</b> |



***SURVEYOR'S  
RECOMMENDATIONS***

---

***\$ 360.00***

---

***\$ 360.00***

---


**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKQ 2722 S**

| S/N                         | NATURE OF JOBS                                                                                                                                                                            |            | ESTIMATED CHARGES   | SURVEYOR'S RECOMMENDATIONS |                 |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|---------------------|----------------------------|-----------------|
|                             |                                                                                                                                                                                           | <i>c/f</i> |                     | \$                         | <b>360.00</b>   |
| 6                           | TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.                               | S/N        | \$ 1,400.00         |                            |                 |
| 7                           | TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.                           |            | \$ 4,000.00         | \$                         | <b>750.00</b>   |
| 8                           | TO RESPRAY REAR BUMPER, REAR LID, RHS REAR FENDER, DOOR ENTRANCES, RHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS. |            | \$ 4,000.00         | \$                         | <b>1,100.00</b> |
| 9                           | TO CARRY OUT PRE AND POST WHEEL ALIGNMENT. TO RENEW RHS REAR RIM.                                                                                                                         | S/N        | \$ 520.00           | \$                         | <b>260.00</b>   |
| 10                          | TO TOW VEHICLE FROM ACCIDENT SCENE                                                                                                                                                        | S/N        | \$ 280.00           |                            |                 |
| 11                          | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                            | S/N        | \$ 192.00           | \$                         | <b>192.00</b>   |
| 12                          | TO RE-APPLY PAINT COATING.                                                                                                                                                                | S/N        | PRICE TBC           |                            |                 |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                           | :          | <b>\$ 13,352.00</b> | <b>\$</b>                  | <b>2,662.00</b> |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKQ 2722 S**

| S/N                          | PARTS DESCRIPTION                       | QTY | DAMAGED PARTS & PRICES |                 | REMARKS            |
|------------------------------|-----------------------------------------|-----|------------------------|-----------------|--------------------|
|                              |                                         |     | S/NETT                 |                 |                    |
| 1                            | REAR BUMPER                             |     | \$                     | 2,181.00        | \$ 1,744.80        |
| 2                            | REAR BUMPER FIXING PARTS                |     | \$                     | 72.00           |                    |
| 3                            | REAR BUMPER SECURING STRIP              |     | \$                     | 220.00          | \$ 176.00          |
| 4                            | REAR BUMPER SPOILER                     |     | \$                     | 246.00          | \$ 196.40          |
| 5                            | REAR LIGHT REFLECTOR - RH               |     | \$                     | 41.00           |                    |
| 6                            | LED TAIL LIGHT - RH                     |     | \$                     | 1,008.00        |                    |
| 7                            | TAIL LIGHT TRIM - RH                    |     | \$                     | 30.00           |                    |
| 8                            | REAR BUMPER GUIDE SECTION - TH          |     | \$                     | 45.00           | \$ 35.36           |
| 9                            | REAR BUMPER GUIDE SECTION - LH / RH     | 2   | \$                     | 44.00           |                    |
| 10                           | REAR BUMPER CARRIER                     |     | \$                     | 886.00          |                    |
| 11                           | REAR BUMPER CARRIER SEAL                | 2   | \$                     | 28.00           |                    |
| 12                           | REAR PARKING AID SENSOR - INNER / OUTER | 2   |                        | TBC             |                    |
| 13                           | REAR PARKING AID SEAL RING              | 4   | \$                     | 14.00           |                    |
| 14                           | BOOT LID CONTROL UNIT                   |     | \$                     | 399.00          |                    |
| 15                           | REAR FENDER - RH                        |     | \$                     | 2,644.00        |                    |
| 16                           | REAR WINDSCREEN                         |     | \$                     | 1,141.00        |                    |
| 17                           | SIDE WINDOW - RH                        |     | \$                     | 609.00          |                    |
| 18                           | PRIMER                                  |     | \$                     | 19.00           |                    |
| 19                           | VENT TRIM                               |     | \$                     | 66.00           |                    |
| 20                           | WHEEL HOUSINF LINER - RH                |     | \$                     | 237.00          | \$ 189.20          |
| <b>SUB TOTAL SPARE PARTS</b> |                                         | :   | \$                     | <b>9,930.00</b> | <b>\$ 2,341.76</b> |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKQ 2722 S**

| S/N PARTS DESCRIPTION |                         | QTY | DAMAGED PARTS & PRICES |           |             |
|-----------------------|-------------------------|-----|------------------------|-----------|-------------|
|                       |                         |     | S/NETT                 | REMARKS   |             |
|                       |                         | c/f |                        | \$        | 2,341.76    |
| 21                    | WHEEL HOUSING LINER     |     | \$                     | 90.00     |             |
| 22                    | AUDI EMBLEM             |     | \$                     | 122.00    |             |
| 23                    | A4 INSCRIPTION          |     | \$                     | 95.00     |             |
| 24                    | TFSI INSCRIPTION        |     | \$                     | 95.00     |             |
| 25                    | PACKING ADHESIVE        |     | \$                     | 18.00     |             |
| 26                    | REAR NO PLATE           | S/N | \$                     | 60.00     |             |
| 27                    | REAR WINDSCREEN SEALANT | S/N | \$                     | 200.00    |             |
| 28                    | REAR RIM - RH           |     | \$                     | 730.00    | \$ 730.00   |
| 29                    | 1/4 GLASS SEALANT       | S/N | \$                     | 100.00    |             |
| 30                    | METAL FILLER POWDER     | S/N | \$                     | 280.00    |             |
| 31                    | STONE CHIP              | S/N | \$                     | 180.00    |             |
| 32                    | CAVITY WAX              | S/N | \$                     | 140.00    |             |
| 33                    | ACRYLIC SEALANT         | S/N | \$                     | 180.00    |             |
| 34                    | SUNDRIES                |     | \$                     | 350.00    |             |
| TOTAL SPARE PARTS     |                         | :   | \$                     | 12,570.00 | \$ 3,071.76 |
| TOTAL LABOUR CHARGES  |                         | :   | \$                     | 13,352.00 | \$ 2,662.00 |
| GRAND TOTAL           |                         | :   | \$                     | 25,922.00 | \$ 5,733.76 |

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-03/11/20

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT