

SK Automobile Pte. Ltd.
 (Co Reg. No. 201500047H)
 8 Kaki Bukit Ave 4 #08-45/46
 Premier@Kaki Bukit S(415875)
 Tel : 6789 5155 Fax : 6783 5155

TO	: AIG	DATE	: 27-Sep-20
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT	:		
<u>OWNER PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO.	: SMK3505D
ADDRESS	:	MODEL / MAKE	: HYUNDAI AVANTE
TEL. NO.	:	CHASSIS NO.	: KMHD841CMKU885187
OWNER INSURANCE	: AXA	<u>ACCIDENT DETAIL</u>	
POLICY NO.	: P2273205	DATE	: 7-Aug-20
		TIME	: 18:00hrs
PERSON INCHARGE	:		

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Repaired</i>	1	\$ 474.90	\$ 474.90
2	FRONT BUMPER SIDE RETAINR LH/RH <i>2x new</i>	2	\$ 23.80	\$ 47.60
3	FRONT BUMPER SJDE AIR VENT RH <i>Repaired</i>	1	\$ 35.70	\$ 35.70
4	FRONT BUMPER SIDE AIR VENT INNER GUIDE RH <i>Repaired</i>	1	\$ 38.50	\$ 38.50
5	FRONT BUMPER SIGNAL LAMP RH <i>Repaired</i>	1	\$ 164.60	\$ 164.60
6	FRONT HEADLAMP RH <i>Repaired</i>	1	\$ 1,198.70	\$ 1,198.70
7	FRONT HEADLAMP LOWER BRACKET RH <i>Repaired</i>	1	\$ 28.40	\$ 28.40
TOTAL PRICE				\$ 1,988.40
LESS -20%				\$ (397.68)
SUB TOTAL PRICE				\$ 1,590.72

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS SET <i>new</i>	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER SIDE AIR VENT INNER GUIDE CLIPS SET RH <i>new</i>	1	\$ 30.00	\$ 30.00
3	FRONT HEADLAMP CLIPS SET RH <i>Not New</i>	1	\$ 40.00	\$ 40.00
TOTAL				\$ 150.00

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 400.00	200	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 400.00	200	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 50.00	X	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	X	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	X	

TOTAL \$ 1,290.00

430

ESTIMATE REPORT

TOTAL PARTS COST	:	\$ 1,740.72
TOTAL LABOUR COST	:	\$ 1,290.00
TOTAL REPAIR COST	:	\$ 3,030.72

Adnan Lj
28/09/20 4/s-

03 days

total: 1060

4/s: 850

APPROVED DETAILS

NO. OF REPAIR DAYS	:	DAYS
REPAIR UNDER	:	PART BY PART OR LUMP SUM
DATE / TIME OF SURVEY	:	
SURVEYED BY / FROM	:	
CONTACT NUMBER	:	
FAX NUMBER	:	
EMAIL ADDRESS	:	
DATE / TIME OF RE-SURVEY	:	
EXCESS	:	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: