

P/P = \$ 28,665.08
12 repair days

SERVICE ESTIMATE

93425 - C00001 SL: SERVICE SALES - PC
Mr Goh Jing Jie
32 Tai Hwan Crescent
Singapore 555593

GST Reg.No: M28920628X
Inv.No. : B3P 0 Page 1
Inv.date : 25/09/2020
WIP No. : 41522
Veh.In/Out:
*Tel.No. : Mobile: 97594693
Reg.No. : SKF6182G
Reg.date : 07/11/2017
Mileage : 0
Chassis No: SAJAB4AN2JCP29845

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Goh Jing Jie

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER, RADIATOR GRILLE, BUMPER BEAM, REAR BUMPER, REAR RH QTR PANEL, 900 REAR VALANCE, END PANEL REPAIR REAR RH DOOR, ETC	0		8100.00	0		8,100.00 S	5850 ✓
800	TO SPRAYPAINT & BLEND ON FRT BUMPER, REAR BUMPER, 800 REAR END PANEL, REAR RH QTR PANEL, REAR RH DOOR	0		5600.00	0		5,600.00 S	3200 ✓
302	TO REPLACE REAR WINDSCREEN	0		900.00	0		900.00 S	600 ✓
0080	TO INSTALL REAR WINDSCREEN FIL	0		280.00	0		280.00 S	✓ 280.00 S
302	TO REMOVE, REFIT CARPET LINING INTERIOR TRIMMING, REAR BOOT INTERIOR	0		2700.00	0		2,700.00 S	1350 ✓
237	TO REPLACE REAR UNDERCARRIAGE	0		2800.00	0		2,800.00 S	✓ 2800.00 S
0031	TO REPLACE REAR RH TYRE	0		700.00	0		700.00 S	400 ✓

(Photo of 11mm)
\$900

70%

28/9/17, 3.00pm
 Steve (LKK) ML P/P
 12 days
 P/P, Rg Bof Sj

SERVICE ESTIMATE

93425 - 000001 SL: SERVICE SALES - PC

Mr Goh Jing Jie
 32 Tai Hwan Crescent

Singapore 555593

Closed by : Paul Ong Wing Yong
 Svc Consultant :
 Remarks : Mr Goh Jing Jie

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 2

Inv.date : 25/07/2020

WIP No. : 41522

Veh.In/Out:

*Tel.No. : Mobile: 97594693

Reg.No. : SKF6187G

Reg.date : 07/11/2017

Mileage : 0

Chassis No: SAJAB4AN2JCP29845

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
0031	TO REPLACE REAR RH RIM	0		50.00	0		50.00 S	✓
419	WHEEL ALIGNMENT	0		280.00	0		280.00 S	✓
280	TO FOCUS HEADLAMP	0		175.00	0		175.00 S	✓
280	TO CHECK WIRING INCLUDE	0		525.00	0		525.00 S	✓
	RESETTING OF ALL ELECTRICAL							
	MODULES							
R06	NUMBER PLATE & HOLDER	0		cut 120.00	0		120.00 S	60 ✓
	(FRONT & BACK)							
	COVER-BUMPER	1.0	EA	1861.00			1,861.00 S	1674.90 ✓
	GRILLE-RADIA	1.0	EA	473.50			473.50 S	426.15 ✓
	BRACKET-FEND RH	1.0	EA	37.10			37.10 S	
	BRACKET-FEND LH	1.0	EA	37.10			37.10 S	
	PANEL-NOSE	1.0	EA	97.30			97.30 S	
	INSERT-FOAM	1.0	EA	57.50			57.50 S	
	JT2H25302/BEAM BUMPE	1.0	EA	953.90			953.90 S	
	WHEEL- 18" Rear Tem	1.0	EA	857.60			857.60 S	771.84 ✓
	COVER BUMPER REAR	1.0	EA	1068.20			1,068.20 S	961.38 ✓

SERVICE ESTIMATE

93425 - C00001 SL: SERVICE SALES - PC
 Mr Goh Jing Jie
 32 Tai Hwan Crescent

Singapore 555593

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Mr Goh Jing Jie

Inv.No. . : B&P 0 Page 3
 Inv.date. : 25/09/2020
 WIP No. . : 41522
 Veh.In/Out:
 *Tel.No. . : Mobile: 97594693
 Reg.No. . : SKF6182G
 Reg.date. : 07/11/2017
 Mileage . : 0
 Chassis No: SAJAB4AN2JCP29845

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

PANEL-VALANC (Pick) - CUT	1.0 EA	491.50	491.50 S	442.35 ✓			
MOUNTING-BRACKET LHR X NN	1.0 EA	115.80	115.80 S	87.48 ✓			
MOUNTING-BRACKET RR / OR	1.0 EA	97.20	97.20 S	✓			
MOUNTING-BRACKET RH / OR	1.0 EA	115.80	115.80 S	104.22 ✓			
BUMPER BEAM REAR XE X NN	1.0 EA	607.30	607.30 S				
PARKING AID SENSOR R / OR	1.0 EA	236.50	1,419.00 S	212.85 ✓			
QUARTER PANEL REAR R / OR	1.0 EA	1672.10	1,672.10 S	1,504.89 ✓			
REAR WINDSCREEN XE / NK	1.0 EA	1183.20	1,183.20 S	1,064.88 ✓			1,064.88
WINDSCREEN SPACER / NK	4.0 EA	8.20	32.80 S	29.52 ✓			
JC2D7026/SEALANT WIN / NK	2.0 EA	159.50	319.00 S	287.10 ✓			
PRIMER / NK	1.0 EA	185.60	185.60 S	167.04 ✓			
FLAP-FUEL FILLER X R	1.0 EA	227.50	227.50 S				
PANEL-REAR XE X R	1.0 EA	647.60	647.60 S				
PANEL-REAR OUTER X R	1.0 EA	1818.60	1,818.60 S				
TAILLAMP RH XE / OR	1.0 EA	430.20	430.20 S	387.18 ✓			
REAR LAMP FOG RH XE X NN	1.0 EA	347.20	347.20 S				
SOUND DEADENING PAD / NK	1.0 EA	525.40	525.40 S	472.86 ✓			

SERVICE ESTIMATE

03425 - 000001 SI: SERVICE SALIS - PC
Mr Goh Jing Jie
32 Tai Hwan Crescent

Singapore 555593

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Goh Jing Jie

GST Reg. No. M28920628X
Inv. No. : BAP 0 Page 4
Inv. date. : 25/09/2020
WIP No. : 41522
Veh. In/Out:
*Tel. No. : Mobile: 97594693
Reg. No. : SKF 61876
Reg. date. : 07/11/2017
Mileage : 0
Chassis No: SAJAB4AN7JCP29845

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	3M07333 IMPACT RESIS	1.0 EA	84.10			84.10 S	
	3M08115 PANEL BONDIN	1.0 EA	68.30			68.30 S	
	VLINER-WHEELARCH RHR	1.0 EA	259.90			259.90 S	
	DUCT-GRILLE RHR	1.0 EA	52.80			52.80 S	
	ADHESIVE SEALER FL2	1.0 EA	703.00			703.00 S	
	BODY PANEL SEALANT X	1.0 EA	928.00			928.00 S	

75.69 ✓
61.47 ✓
233.41 ✓
47.52 ✓
632.70 ✓

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Total 22,230.00
Parts Total 17,775.10
Package Total 0.00

Gross Total. 40,005.10

Net..... 40,005.10

GST @ 7.0% 2,800.36

Total..... 42,805.45

Paid..... 0.00

Please Pay.. 42,805.45

GST: S=Standard; O=Out of Scope; Z=Zero Rated

SERVICE ESTIMATE

0 - I00012 SL: INDIA INTERNATIONAL INSURANCE
 INDIA INTERNATIONAL INSURANCE
 64 CECIL ST
 #04-05 IOB BUILDING
 SINGAPORE 049711

GST Reg.No: M28920628X
 0 Page 3
 Inv.No. : B&P
 Inv.date. : 20/11/2020
 WIP No. : 41522
 Veh.In/Out: 30/09/2020 04/11/2020
 *Tel.No. : 6347 6100
 Reg.No. : SKF6182G
 Reg.date. : 07/11/2017
 Mileage : 71,305
 Chassis No: SAJAB4AN2JCP29845

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Mr Goh Jing Jie

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	3M07333 IMPACT RESIS <i>NEC</i>		1.0 EA	84.10	10	/	75.69	S
	3M08115 PANEL BONDIN <i>NEC</i>		1.0 EA	68.30	10	/	61.47	S
	V-LINER-WHEELARCH RHR <i>CR4</i>		1.0 EA	259.90	10	/	233.91	S
	DUCT-GRILLE RHR <i>OR</i>		1.0 EA	52.80	10	/	47.52	S
	ADHESIVE SEALER FL2 <i>NEC</i>		1.0 EA	703.00	10	/	632.70	S
	GESTURE MODULE-CONTR <i>OR</i>		1.0 EA	343.20	10	/	308.88	S ✓
	LOWER GESTURE SENSOR <i>OR</i>		1.0 EA	470.40	10	/	423.36	S ✓
	UPPER GESTURE SENSOR <i>OR</i>		1.0 EA	387.50	10	/	348.75	S ✓
	INSERT-FOAM <i>OR</i>		1.0 EA	57.50	10	/	51.75	S ✓
	INSERT <i>OR</i>		1.0 EA	24.10	10	/	21.69	S ✓
	BEAM-BUMPER <i>OR</i>		1.0 EA	953.90	10	/	858.51	S ✓
	HEADLAMP LH <i>OR</i>		1.0 EA	3641.80	10	/	3,277.62	S ✓
	PANEL-EXTENSION <i>CR4</i>		1.0 EA	107.00	10	/	96.30	S ✓
	MOUNTING-BRACKET <i>OR</i>		1.0 EA	97.20	10	/	87.48	S ✓
	HARNES REAR <i>TN</i>		1.0 EA	430.80	10	/	387.72	S ✓
	RIVET FSC4850 4.8X5 <i>NEC</i>		30.0 EA	3.00	10	/	81.00	S ✓
	RIVET FSC4870 4.8X7 <i>NEC</i>		5.0 EA	2.40	10	/	10.80	S ✓



SERVICE ESTIMATE

GST Reg.No:M28920628X

0 Page 4
Inv.No. : B&P
Inv.date. : 20/11/2020
WIP No. : 41522
Veh.In/Out: 30/09/2020 04/11/2020
*Tel.No. : 6347 6100
Reg.No. : SKF6182G
Reg.date. : 07/11/2017
Mileage : 71,305
Chassis No: SAJAB4AN2JCP29845

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
Remarks : Mr Goh Jing Jie								

Op.No	Description	Mech Qty	Price	Total
	RIVET MC	3.0 EA	1.80 10 /	4.86 S
	RIVET MC	8.0 EA	1.70 10 /	12.24 S
	RIVET 5.3mmx7.0mm MC	10.0 EA	1.80 10 /	16.20 S
	RIVET MC MC	3.0 EA	2.40 10 /	6.48 S
	RIVET 5.5X5 MC	5.0 EA	1.80 10 /	8.10 S
	RIVET MC	5.0 EA	3.30 10 /	14.85 S
	RIVET MC	10.0 EA	1.60 10 /	14.40 S
	RIVET 6.5X13X20 XJL MC	10.0 EA	6.20 10 /	55.80 S
	RIVET 6.5X13X17.5 XJ MC	10.0 EA	3.40 10 /	30.60 S
	RIVET 6.5X13X16 XJL MC	10.0 EA	1.60 10 /	14.40 S
	RIVET MC	10.0 EA	3.30 10 /	29.70 S
	SHIELD-DEFLE BR	1.0 EA	94.60 10 /	85.14 S
	TAILLAMP RH XE BR	1.0 EA	430.20 10 /	387.18 S

Labour	Total	12,860.00
parts	Total	15,805.08
package	Total	0.00

Gross Total.	28,665.08
Net.....	28,665.08
GST @ 7.0%	2,006.56
Total.....	30,671.64
Paid.....	0.00
please Pay..	30,671.64

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Wearnes Automotive Pte. Ltd.
 45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com
 Co reg no. 199501400R / GST reg no. M28920628X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: