

Section A - Accident Details

Registration Number	SHC4651J
Case Reference Number	TAX/09/20/2059
Registration Date	19/9/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	CHUA THIAM HUAT
Type of Accident	Side Swipe
Accident Date and Time	23/9/2020 1 22 PM
Accident Reported Date and Time	23/9/2020 3 19 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108261
Special Instruction to ARC, if any	LEFT SIDE PORTION DAMAGE
Prepared Date and Time	24/9/2020 1:39 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$600.00
Total Spray Cost	\$1,494.00	\$750.00
Total Spare Part Cost	\$3,506.79	\$2,097.27
Total Other Cost	\$1,305.00	(\$347.27)
TOTAL COST	\$7,319.79	\$3,100.00 (L/S)
Lump Sum Total	\$7,300.00	\$0.00
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Kim Ming Chin	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	28/09/2020 3:15 PM	28/09/2020 3:05 PM
Signature		
Remarks	Total number of repair days = 4 days SUP = 0 day	
	L/S. After paint photo	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2010-0142	Invoice Number	
Quotation Date	12.10.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$600.00
Total Labour	\$1,014.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY SILL MEMBER PANEL LH	\$180.00	\$100.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,494.00	\$750.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$125.00
TO REMOVE AND REFIT REAR SEAT TO FACILITATE REPAIR	\$120.00	\$30.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$30.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$60.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$50.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO WASH AND VACUUM	\$60.00	(\$772.27)
Total Other Costs	\$1,305.00	(\$347.27)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given X
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace ✓
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given ✓
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 12/10/2020

User ID PohSuan

	42450-47040	WHEEL HUB REAR	0 00	\$489.40	0 00	\$0.00	Replace	Not Given	X
		SEALANT W/SCREEN	1 00	\$37.00	0 00	\$37.00	Replace	Replace	✓
	62720-47031	QUARTER GLASS RR/LH	1 00	\$168.10	25 00	\$126.08	Replace	Replace	✓
		STICKER DECAL 6555 8888	1.00	\$21.60	0 00	\$21.60	Replace	Replace	✓
		STICKER DECAL SMRT	1 00	\$7.80	0 00	\$7.80	Replace	Replace	✓
	61602-47091	FENDER RR/LH	1 00	\$766.80	25 00	\$575.10	Replace	Replace	✓
	52159-47905	BUMPER REAR	1 00	\$458.60	25 00	\$343.95	Replace	Replace	✓
	42611-47140	WHEEL DISC.	1.00	\$1,484.20	100 00	\$0.00	Replace	Repair	✓
	75852-47900	MOULDING BODY, LH	1.00	\$673.60	100 00	\$0.00	Replace	Repair	✓
	67004-47080	DOOR RR/LH	1 00	\$954.50	25 00	\$715.88	Replace	Replace	✓
Total				\$5,559.11		\$2,030.59			✓

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52592-47021	BUMPER SEAL, RR LH	1 00	\$88.90	25 00	\$66.68	Replace	Replace
Total					88.90		66.68		

/CRA

8471.01

2097.27 /
 + 600.00 /
 + 1175.00 /

 3872.27 /
 - 206 /

 3097.82 /
 415 \$3100 /- /
 4 days