

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : ☐ Own Damage

☒ 3rd Party

☐ Windscreen

Vehicle No. : SLE1708S

Make & Model : HONDA / VEZEL 1.5X CVT

Year of Manufacture : 2016

Chassis No. : RU11201623

Engine No. : L15B4401623

Policy No. :

Time of Accident : 07.15 A/M

Ins Company : AIG INS

Excess : TBA

Date of Accident : 25/09/2020

Suggested Days of Repair : 10 DAY

In-house Vehicle Assessor

**Repair Estimates**

Name : Wong Chee Wei

Signature :

Contact No : 6867 6924

Parts (a) Cost Price Items \$6,511.24

Less 20 % \$(1,302.25)

(b) Nett Price Items

Less %

(c) Special Nett Items \$760.00

**Total Parts Cost (Appendix A) \$5,968.99**

**Labour (Appendix B) \$2,710.00**

**Total Repair Cost \$8,678.99**

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Name of Surveyor : Taufik

Company : LKK

Survey conducted on : 1/10/20 at

**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice. WP

(b) Recommended Days of Repair : 4-5 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : Taufik

Date: 1/10/20

## COMFORTDELGRO ENGINEERING PTE LTD

45 Pandan Road S (609286)

Tel: 6867 6924 Fax: 6262 4113

Appendix A

**Spare Parts**

Vehicle No. : **SLE1708S** Submit By : **Wong Chee Wei**  
 Make & Model : **HONDA VEZEL 1.5X CVT** Year Manufacture : **2016**  
 Chassis No. : **RU11201623** Engine No. : **L15B4401623**

**TP**

S/Order : \_\_\_\_\_

S/No	Part Description	Qty	Cost	Nett	List	S- Nett	Disposition By
			G Price	Price	Price	Price	Surveyor
1	REAR WINDSCREEN	1	\$1,300.50				X
2	REAR WINDSCREEN MOULDING SET	1	\$171.82				nei ✓
3	SEALANT REAR WINDSCREEN	2				\$40.00	nei ✓
4	INNER SEAL TAPE REAR WINDSCREEN	1				\$40.00	nei ✓
5	TAIL GATE	1	\$1100.90				bt ✓
6	LOGO - HONDA	1	\$27.10				nei ✓
7	EMBLEM - VEZEL	1	\$65.00				nei ✓
8	REAR BUMPER	1	\$508.72				dei ✓
9	CLIP REAR BUMPER	10	\$39.00				nei ✓
10	L/ REAR SIDE RETAINER	1	\$25.70				x
11	R/ REAR SIDE RETAINER	1	\$25.70				x
12	REAR END PANEL	1	\$4,141.80				fx
13	REAR END PANEL GARNISH	1	\$95.00				?
14	SENSOR REAR BUMPER SET	1				\$300.00	2co nw ✓
15	REAR WINDSCREEN SOLAR FILM	1				\$300.00	? plus ✓
16	BODY SEALANT	1				\$80.00	λ
17		1					
18		1					
19		1					
20		1					
21		1					
22		1					
23		1					
24		1					
25		1					
26		1					
27		1					
28		1					
29		1					
30		1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

## Appendix B

Tel: 63697362 Fax: 63658520

Vehicle No. : SLE1708S Submit By : : Wong Chee Wei  
Make & Model : HONDA Year of Manufacture : 2018

[illegible]