

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

ALG

Owner : Medusa Leasing

Accident Date : 19-Sep-20

Vehicle No : FBE892S

Vehicle Model : Yamaha
T135

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
2	Front fork tube assy <i>2 set LR 80</i>	\$ 640.00 X
1	Fork under bracket <i>11</i>	\$ 185.00 X
1	Front rim shaft <i>11</i>	\$ 45.00 X
1	Front rim bearing <i>11</i>	\$ 38.00 X
1	Handle-bar <i>2 set</i>	\$ 88.00 ?
1	Side mirrors (1 set) <i>CU7</i>	\$ 110.00 ✓
1	Clutch lever <i>scr</i>	\$ 32.00 ✓
2	Front signals <i>11</i>	\$ 140.00 X
1	Headlamp <i>11</i>	\$ 185.00 X
1	Fairing assy (1 set) <i>CU7</i>	\$ 525.00 ✓
1	Front footrest bracket <i>2 set</i>	\$ 65.00 ✓
2	Front footrest rubber - R/H <i>70.00</i>	\$ 70.00 ✓
1	Gear pedal <i>2 set</i>	\$ 42.00 ✓
2	Rear footrest <i>scr</i>	\$ 80.00 X
2	Rear footrest bracket <i>11</i>	\$ 156.00 X
1	Side stand <i>11</i>	\$ 75.00 X
1	Main stand <i>11</i>	\$ 95.00 X
		\$ 2,571.00
Less 10%		\$ 257.10
		\$ 2,313.90
<u>Special Net Items</u>		
1	Number plate (1 set) <i>11</i>	\$ 28.00 X
2	Fork oils <i>11</i>	\$ 30.00 X
2	Fork oil seals <i>11</i>	\$ 56.00 X
1	Steering cone (1 set) <i>CU7</i>	\$ 90.00 ✓
1	Rear box <i>11</i>	\$ 120.00 ✓
1	Front tyre <i>11</i>	\$ 180.00 X
		\$ 504.00

*not attached
2 set
4/5/20
28/9/20*

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Medusa Leasing

Accident Date : 19-Sep-20

Vehicle No : FBE892S

Vehicle Model : Yamaha
T135

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service	\$ 11 50.00 X
2	To ckeck wiring and reset headlamp focusing	\$ 11 80.00 X
3	To provide labour	\$ 250 380.00
4	To repair body frame	\$ 11 350.00 X
		\$ 860.00
Grand Total		\$ 3,677.90

Singapore Dollars: Three Thousand Six Hundred Seventy-Seven and Cents: Ninety only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: