

(08/11/13) wef

ASS. REC. BY: MARUS

REF:

CC4/A1620010372/UG3**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBC 8926

at Workshop m/s

Erofia

of

Insured:

SAL 322A

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

44k

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

P29E

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBC 8926

Yr Regn:

11 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha T135

c.c

135

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

94453

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

51/P301446

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Brim / STD A/Rim or

Tyre Size:

F: 70-90-17 MAXXISR: 80-90-17 Dunlop

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

19/9/20

D.O.I.

28/9/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MA 1258 car 31-8-20241/10/20 2/541150 confirmed with MR TEO

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) \$ + RS. SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

)

TOTAL

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

A16

Owner : Medusa Leasing

Accident Date : 19-Sep-20

Vehicle No : FBE892S

Vehicle Model : Yamaha
T135

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
2	Front fork tube assy 2 set 1.0 B2 R	\$ 640.00 X
1	Fork under bracket 11	\$ 185.00 X
1	Front rim shaft 11	\$ 45.00 X
1	Front rim bearing 11	\$ 38.00 X
1	Handle-bar Bent	\$ 88.00 ✓
1	Side mirrors (1 set) 11	\$ 110.00 ✓
1	Clutch lever 11	\$ 32.00 ✓
2	Front signals 11	\$ 140.00 X
1	Headlamp 11	\$ 185.00 X
1	Fairing assy (1 set) 11	\$ 525.00 ✓
1	Front footrest bracket Bent	\$ 65.00 ✓
2	Front footrest rubber - R/H Torn	\$ 70.00 ✓
1	Gear pedal Bent	\$ 42.00 ✓
2	Rear footrest 11	\$ 80.00 X
2	Rear footrest bracket 11	\$ 156.00 X
1	Side stand 11	\$ 75.00 X
1	Main stand 11	\$ 95.00 X
		\$ 2,571.00
Less 10%		\$ 257.10
		\$ 2,313.90
<u>Special Net Items</u>		
1	Number plate (1 set) 11	\$ 28.00 X
2	Fork oils 11	\$ 30.00 X
2	Fork oil seals 11	\$ 56.00 X
1	Steering cone (1 set) 11	\$ 90.00 ✓
1	Rear box 11	\$ 120.00 ✓
1	Front tyre 11	\$ 180.00 X
1	ERP in unit cut (should 200 175 / S.N)	\$ 504.00

Not Affected
28/9/20

P. 932
11/2
83880

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Owner : Medusa Leasing

Accident Date : 19-Sep-20

Vehicle No : FBE892S

Vehicle Model : Yamaha
T135

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service	\$ 11	50.00 X
2	To ckeck wiring and reset headlamp focusing	\$ 11	80.00 X
3	To provide labour	\$ 250	380.00
4	To repair body frame	\$ 11	350.00 X
		\$	860.00
Grand Total		\$	3,677.90

Singapore Dollars: Three Thousand Six Hundred Seventy-Seven and Cents: Ninety only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1473-8
1119.