

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TING SENG CEREMONIAL PRODUCTS
 38 BEO CRESCENT #01-48 THE BEO
 CRESCENT
 SINGAPORE 160038

Contact : 91086215

TR III

Xiao Tony

ESTIMATE

Repair Code : CLM16462

Date in : 28/09/2020

Vehicle Num. : GBB5096G

Model : TOYOTA HIACE MANUAL

Chassis/Eng# : JTFHT02P400042120/1KD1921538

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Defect</i>	1	695.90	✓ 695.90
REAR BUMPER LOWER BRACKET <i>2 piece bent</i>	4	30.00	60. ✓ 120.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	60.87	✓ 121.74
REAR END PANEL (INNER) <i>Defect</i>	1	859.50	✓ <u>859.50</u>
REAR END PANEL (OUTER) <i>Defect</i>	1	388.27	✓ 388.27
REAR END PANEL TOP PLATE <i>Not in</i>	1	180.71	x 180.71
REAR END PANEL TOP PLATE SIDE COVER L/R <i>new</i>	2	38.25	x 76.50
REAR LH FENDER <i>Repair</i>	1	1087.58	x 1,087.58
REAR LH FENDER INNER AIR VENT <i>could</i>	1	58.00	✓ 58.00
REAR TAILGATE <i>Defect</i>	1	1890.54	✓ 1,890.54
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	85.87	✓ 85.87
REAR TAILGATE HINGES L/R <i>Not in</i>	1	96.57	x 193.14
REAR TAILGATE INNER LOCK CONTROL ASSY <i>Not in</i>	2	290.95	x 290.95
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>new</i>	1	48.70	x 97.40
REAR TAILGATE LOCK STRIKER <i>new</i>	2	68.57	x 68.57
REAR TAILGATE MECHANISM LOCK <i>Defect</i>	1	235.00	✓ 235.00
REAR TAILGATE WEATHER STRIP <i>cut</i>	1	395.90	✓ 395.90
REAR TAILLAMP L/R <i>LH could</i>	2	395.80	395.80 x 791.60

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TING SENG CEREMONIAL PRODUCTS
38 BEO CRESCENT #01-48 THE BEO
CRESCENT
SINGAPORE 160038

Contact : 91086215

ESTIMATE

Repair Code : CLM16462

Date in : 28/09/2020

Vehicle Num. : GBB5096G

Model : TOYOTA HIACE MANUAL

Chassis/Eng# : JTFHT02P400042120/1KD1921538

REAR TAILLAMP LOWER GARNISH L/R	LH Del	2	88.63	88.63	177.26
REAR TAILLAMP LOWER GARNISH SIDE RETAINER L/R	new	2	50.84	+	101.68
Subtotal before discount			3958.61		7,916.11
Percentage discount 25%					1,979.03
Sub-total 1					5,937.08
REAR BUMPER CLIPS - SET	new	1	80.00	30	80.00
REAR TAILGATE '70KM' STICKER	new	1	25.00	15	25.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	new	1	50.00	+	50.00
REAR TAILGATE NUMBER PLATE	new	1	25.00	+	25.00
REAR TAILGATE OUTER HANDLE CLIPS - SET	new	1	30.00	+	30.00
REAR TAILGATE WINDSCREEN SEAL	new	1	80.00	40	80.00
REAR TAILGATE WINDSCREEN SEALANT	new	1	80.00	40	80.00
REAR TAILLAMP CLIPS L/R - SET	new	2	25.00	15	50.00
Subtotal before discount					420.00
Percentage discount 0%					0.00
Sub-total 2					420.00
Parts-total					6,357.08

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TING SENG CEREMONIAL PRODUCTS
38 BEO CRESCENT #01-48 THE BEO
CRESCENT
SINGAPORE 160038

Contact : 91086215

ESTIMATE

Repair Code : CLM16462

Date in : 28/09/2020

Vehicle Num. : GBB5096G

Model : TOYOTA HIACE MANUAL

Chassis/Eng# : JTFHT02P400042120/1KD1921538

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

50 80.00
120 150.00
50 120.00
80 1,000.00
80 1,200.00
60 80.00
60 80.00

1940

Labour Total

2,710.00

Parts & Labour Total

9,067.08

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
2/s 29/09/20
06 Days
Total: 6038.61
N/s : 48K. ✓