

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 28-Sep-20

INSURANCE: ALG

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 7241 A

Description	Qty	List Price	Amount
Front Bumper Cover torn	1	\$ 418.30	\$ 418.30
Front Bumper Bracket (LH) HH	2	\$ 28.00	\$ 56.00
Front Bumper Retainer Mounting (LH) CRACK / broken	1	\$ 65.30	\$ 65.30
Front Bumper Clips 10 pcs Nec	1	\$ 25.00	\$ 25.00
Front Bumper Grille (LH) HH	1	\$ 186.90	\$ 186.90
Front bumper air duct (LH) HH	1	\$ 153.80	\$ 153.80
Day Light ,LH & mostly broken	1	\$ 642.50	\$ 642.50
Day Light Wire, LH HH	1	\$ 585.50	\$ 585.50
BUZZER ASSY - PIEZO (LH) HH	1	\$ 388.00	\$ 388.00
Headlamp Support Panel Assy & CRACK	1	\$ 949.30	\$ 949.30
Headlamp(LH) broken	1	\$ 3,987.30	\$ 3,987.30
Front Fender(LH) Dented	1	\$ 490.70	\$ 490.70
Front Fender Apron Panel (LH) HH	1	\$ 756.20	\$ 756.20
Front Fender Apron Panel Upper(LH) HH	1	\$ 229.60	\$ 229.60
Front Fender Shield (LH) damaged	1	\$ 164.70	\$ 164.70
Frt Door(LH) 1st (Dented)	1	\$ 1,797.20	\$ 1,797.20
Frt Door Rubber HH	1	\$ 250.00	\$ 250.00
Front Door Hinge Upper (LH) HH	1	\$ 165.76	\$ 165.76
Front Door Hinge Lower (LH) HH	1	\$ 153.70	\$ 153.70
Front Door Check (LH) HH	1	\$ 72.98	\$ 72.98
Front Door Mirror ASSY (LH) vgn	1	\$ 1,391.70	\$ 1,391.70
Front Door Protector(LH) cnt	1	\$ 186.20	\$ 186.20
Rocker Panel Outer Garnish & 1st / mostly broken	1	\$ 715.60	\$ 715.60
Front Wheel Rim (LH) & distortion	1	\$ 1,124.20	\$ 1,124.20
Front Wheel hub assy (LH) & Down	1	\$ 678.50	\$ 678.50
Front Wheel Hub Cap (LH) cnt	1	\$ 289.80	\$ 289.80
Front Shock Absorber(Assy)(LH) & distortion	1	\$ 372.50	\$ 372.50
Front Shock Absorber Mounting (LH) HH	1	\$ 206.90	\$ 206.90
Front Drive Shaft (LH) HH	1	\$ 1,136.70	\$ 1,136.70
Front drive shaft extension LH HH	1	\$ 1,125.80	\$ 1,125.80
Rack & Pinion Assy HH	1	\$ 1,087.40	\$ 1,087.40
STG Tie Rod & HH	1	\$ 125.60	\$ 125.60
STG Tie End & HH	1	\$ 94.70	\$ 94.70
Stabilizer Bar HH	1	\$ 326.80	\$ 326.80
Stabilizer Bar Link HH	1	\$ 92.10	\$ 92.10
Front Suspension Lower Arm (LH) & distortion	1	\$ 596.80	\$ 596.80
Knuckle Arm (LH) & distortion	1	\$ 663.60	\$ 663.60
SUB TOTAL			\$ 21,753.64
LESS 20%			\$ 4,350.73
DISCOUNTED TOTAL			\$ 17,402.91

Emblem-Blue Drive (LH) <i>NCC</i>	SN	1	\$ 26.60	\$ 26.60	<i>✓</i>
Front Door Comfort Logo (LH) <i>NCC</i>	SN	1	\$ 75.00	\$ 75.00	<i>✓</i>
Front Tyre(LH) <i>HH</i>	SN	1	\$ 216.00	\$ 216.00	<i>X</i>
SUB TOTAL				\$ 317.60	
Labour Charge					
Panel Beating		1	\$1,400.00	\$1,400.00	<i>700/-</i>
Spray Painting Charge		1	\$1,200.00	\$1,200.00	<i>700/-</i>
Wiring Charge		1	\$160.00	\$160.00	<i>30/-</i>
Tuff Kote		1	\$140.00	\$140.00	<i>40/-</i>
Towing Charge		1	\$80.00	\$80.00	<i>42/-</i>
Transfer of Door Mechanism FRONT		1	\$80.00	\$80.00	<i>60/-</i>
Re-set Frt Power Window System		1	\$200.00	\$200.00	<i>42/-</i>
Four Wheel Alignment		1	\$120.00	\$120.00	<i>60/-</i>
Remove/Refix Undercarriage (Frt)		1	\$400.00	\$400.00	<i>150/-</i>
Re-set Frt ABS System		1	\$200.00	\$200.00	<i>42/-</i>
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	<i>180/-</i>
TOTAL LABOUR				\$4,530.00	
ESTIMATE TOTAL				\$ 22,250.51	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

28/09/2020 @ 1700hrs

Not Actual

Part by P.A.

6 days.

LKK Auto

[Signature]

*Photo of
repair with
damaged part*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR SUPPLEMENTARY

DATE: 29-Sep-20

INSURANCE: ALG

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 7241 A (S)

Description	Qty	List Price	Amount
Front Bumper Moulding Centre Upper <i>st 1 minity grade</i>	1	\$ 368.50	\$ 368.50
SUB TOTAL			\$ 368.50
LESS 20%			\$ 73.70
DISCOUNTED TOTAL			\$ 294.80

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Ryan

2kk Auto

A