

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HDBTERMINAL .
BLK 592C MONTREAL LINK #17-32
SINGAPORE 753592

Contact : 92718723

ESTIMATE

Repair Code : CLM16463

Date in : 26/09/2020

Vehicle Num. : SMJ2404Z

Model : HONDA SHUTTLE 1.5G CVT ABS D/AIRBAG 2WD 5DR

Chassis/Eng# : GK82001286/L15B6001590

TP 111
Cecilia

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Distorted</i>	1	1050.00	✓ 1,050.00
FRONT BUMPER LOWER GRILLE <i>Deformed</i>	1	140.00	✓ 140.00
FRONT BUMPER LOWER SPOILER <i>He m</i>	1	145.00	X 145.00
FRONT BUMPER RH FOGLAMP <i>Crackd</i>	1	308.90	✓ 308.90
FRONT BUMPER RH FOGLAMP GARNISH <i>Deformed</i>	1	95.00	✓ 95.00
FRONT BUMPER SIDE RETAINER L/R <i>RH Dmgd</i>	2	12.00	12 24.00
FRONT BUMPER TOW HOOK COVER <i>Deformed</i>	1	25.00	✓ 25.00
FRONT CHASSIS SIDE MEMBER RH (INNER) <i>3 Riv</i>	1	75.50	X 75.50
FRONT CHASSIS SIDE MEMBER RH (OUTER)	1	65.50	X 65.50
FRONT GRILLE <i>Crackd</i>	1	395.00	✓ 395.00
FRONT GRILLE OUTER CHROME COVER <i>He m</i>	1	302.50	X 302.50
FRONT GRILLE OUTER CHROME COVER 'LOGO' EMBLEM <i>m</i>	1	23.40	✓ 23.40
FRONT HEADLAMP (LED) L/R <i>RH crackd</i>	2	2250.00	2250 4,500.00
FRONT HEADLAMP LOWER BRACKET L/R <i>RH crackd</i>	2	38.00	38 76.00
FRONT RH EXTENSION PANEL (INNER) <i>3 Buckled</i>	1	94.80	✓ 94.80
FRONT RH EXTENSION PANEL (OUTER)	1	150.00	✓ 150.00
FRONT RH FENDER <i>Dented</i>	1	368.10	✓ 368.10
FRONT RH FENDER INNER SHIELD <i>Deformed</i>	1	110.50	✓ 110.50

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HDBTERMINAL
BLK 592C MONTREAL LINK #17-32
SINGAPORE 753592

Contact : 92718723

ESTIMATE

Repair Code : CLM16463

Date in : 26/09/2020

Vehicle Num. : SMJ2404Z

Model : HONDA SHUTTLE 1.5G CVT ABS D/AIRBAG 2WD 5DR

Chassis/Eng# : GK82001286/L15B6001590

FRONT RH KNUCKLE ARM	1	330.60	X	330.60
FRONT RH KNUCKLE ARM BEARING	1	168.00	X	168.00
FRONT RH SHOCK ABSORBER	1	420.00	X	420.00
FRONT SUPPORT LOWER PANEL	1	180.30	X	180.30
WASHER TANK	1	75.00	✓	75.00
WASHER TANK MOTOR	1	58.50	X	58.50
Subtotal before discount				9,181.60
Percentage discount 20%				1,836.32
Sub-total 1				7,345.28
FRONT BUMPER CLIPS - SET	1	80.00	40	80.00
FRONT BUMPER LOWER SPOILER CLIPS - SET	1	30.00	X	30.00
FRONT GRILLE CLIPS - SET	1	30.00	✓	30.00
FRONT RH FENDER INNER SHIELD CLIPS - SET	1	50.00	30	50.00
FRONT RH SPORT RIM	1	580.00	X	580.00
FRONT RH TYRE	1	300.00	X	300.00
Subtotal before discount				1,070.00
Percentage discount 0%				0.00
Sub-total 2				1,070.00
Parts-total				8,415.28

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

HDBTERMINAL .
BLK 592C MONTREAL LINK #17-32
SINGAPORE 753592

Contact : 92718723

ESTIMATE

Repair Code : CLM16463

Date in : 26/09/2020

Vehicle Num. : SMJ2404Z

Model : HONDA SHUTTLE 1.5G CVT ABS D/AIRBAG 2WD 5DR

Chassis/Eng# : GK82001286/L15B6001590

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

30 80.00

X 150.00

X 100.00

600 1,400.00

700 1,200.00

50 80.00

Labour Total

3,010.00

Parts & Labour Total

11,425.28

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 5668.56

L/s: 4.5K

0.5 Days

4.5K