

Not Authored
11 Sep 8 2300L

Trans-cab Auto Services Pte Ltd

AAD2009-127

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 363L

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

25 SEP 2020

SHD 363L

VF1ABL15AUC282719

RENAULT

LATITUDE

24.9.2020

AIG

17/05/2016

	PART
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	HEADLAMP RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER INSULATOR RH
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	WIPER RESERVOIR
1	ROCKER PANEL OUTER RH
1	SUBFRAME OUTER FRT
1	DOOR PANEL FRT RH
1	DOOR MIRROR ASSY RH
1	DOOR HINGE UPPER FRT RH
1	DOOR HINGE LOWER FRT RH
1	DOOR SEAL FRT RH
1	DOOR WEATHERSTRIP FRT RH

	LIST	
\$	Br / Ins / M / S / C / M	747.20 ✓
\$	SL	344.70 X
\$	DIY	101.40 ✓
\$	SL	292.50 X
\$	SL	147.00 X
\$	SL	207.21 X
\$	SL	743.60 X
\$	R	437.10 ✓
\$	SL	191.40
\$	SL	66.30
\$	SL	969.90
\$	SL	225.36
\$	SL	686.00
\$	R	592.70
\$	SL	179.60
\$	R	1,184.99
\$	SL	1,094.20
\$	R	2,844.66
\$	SL	1,483.40
\$	R	261.28
\$	R	300.55
\$	SL	72.82
\$	SL	410.27
TOTAL	\$	13,584.14
10%	\$	1,358.41
	\$	12,225.73

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 363L

AAD2009-127

Special Nett

1 BUMPER CLIP FRT	\$	nn 90.00	✓
1 BUMPER RETAINER CLIP FRT	\$	nn 75.00	}
1 BUMPER GRILLE LOWER CLIP	\$	nn 75.00	
1SET FRAME FULL SUPPORT PANEL CLIP	\$	nn 70.00	
2 FRAME FULL SUPPORT PANEL NUT	\$	nn 45.00	
2 FRAME FULL SUPPORT PANEL STUD	\$	nn 50.00	
1 WHEELARCH CLIP FRT	\$	nn 75.00	}
1SET Front licence plate with holder	\$	sn 120.00	
1 FRONT RENAULT TYRE RIM	\$	nn 380.00	✓
1SET RADIATOR GRILLE SCREW	\$	nn 55.00	X
1SET RADIATOR GRILLE FRAME CLIP	\$	nn 60.00	X
1 FRONT DOOR STICKER "Trans-Cab"	\$	nn 80.00	601ne ✓
1 FRONT DOOR STICKER "Classic"	\$	nn 80.00	151ne
1 ROCKER PANEL CLIP	\$	nn 60.00	X
1 DOOR SEAL CLIP	\$	nn 55.00	X
TOTAL	\$	1,370.00	

TOTAL PARTS \$ 13,595.73**LABOUR**

To rust-proofing and apply undercoat of the affected areas.	\$	240.00	301
To transfer of door fittings, attachment and perform water seepage test.	\$	nn 170.00	X
Putty and spray painting of the affected portion.	\$	1,400.00	6601
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	1,200.00	4001
To transfer of tire, rim and on wheel balancing.	\$	170.00	201

AAD2009-127

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 363L

To dismantle and refit engine cross-member and engine mounting.

\$ *nn* 380.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 *15h*

To check steering geometry and computer wheel alignment

\$ 220.00 *60h*

TOTAL \$ 3,950.00

Over All Total \$ 17,545.73

LUMP SUM (REPAIR DAY)

15 DAYS

2 1/2 days

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: