



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHUBB INSURANCE SINGAPORE LTD		Ref : CC6/CHB20010383/Aes3q2		
138 MARKET STREET #11-01 CAPITAGREEN SINGAPORE 048946		Date : 08-12-2020		
		Code : CHB		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	Veh. Inspected	SGD 3820B	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	25/09/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA VELLFIRE	c.c	2494
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTNGF3DH608013721	Colour	BLACK
	Odometer	74100	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	235/50 R18	HEADKING	6 mm
	L/H Front Tyre	235/50 R18	HEADKING	6 mm
	R/H Rear Tyre	235/50 R18	HEADKING	6 mm
	L/H Rear Tyre	235/50 R18	HEADKING	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	16/09/2020	Inspection Date	25/09/2020
	Survey held at	PEOPLE'S VEHICLE RECOVERY SERVICE BLK 3023-A, UBI ROAD 1 #01-60 SINGAPORE 408717		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	