

CC6 / AR20010383 / Aes 3

PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717
Tel No. : 67433246 / 67438552 Fax No. : 67430013
E-Mail : peoplevehicle@gmail.com
Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
CHARTIS BUILDING (S) 079120

Attention : Motor Claim Department
Contact : 6419 1826 Fax No. : 6415 3727

Estimate : ES20020

Date : 25/09/2020
Vehicle Num. : SGD 3820 B
Make/Model : TOYOTA VELLFIRE
Chassis/Eng# :
Accident Date : 16/09/2020
Claim No. : TP 384-20
Reference : GBF 8128 H
Policy No. : NTUC 5115429069

Asher

S/N Quantity Particular Unit Price Amount S\$

JTNGF3DH608013721

1.	1	LIST ITEMS :		
2.	1	BUMPER FRT	1,218.90	✓
3.	1	BUMPER SIDE RETAINER L/H FRT	189.20	✓
4.	1	BUMPER SIDE GARNISH L/H FRT	578.10	✓
5.	1	FENDER INNER SHIELD L/H FRT	342.80	✓
6.	7	FENDER INNER SHIELD CLIPS FRT	5.80	✓
List Total S\$:			2,405.00	
25.00% Discount S\$:			601.25	
			1,803.75	

LABOUR :
REMOVE & REPLACE ACCIDENT DAMAGED PARTS
SPRAY PAINTING ACCIDENT EFFECT PARTS
CHECK ALL LIGHTING AFTER REPAIR

Labour Total S\$:

830.00
600.40
600.40
60.00 * 30
810.00

SingDollars : Two Thousand Six Hundred Thirteen & Cents Seventy-Five Only

E. & O.E. Total S\$: 2,613.75

for PEOPLE'S VEHICLE RECOVERY SERVICE

Computer Generated Invoice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1950

Adrian Lj
4/s 25/09/20
03 Days
total: 2465.30
4/s: 1950.