

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16 KFA Auto Consultants (Singapore) Singapore 568047
Tel: 6484 1628 (2 lines) the following 0465
Business Reg. No: 221650/000 GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplier warranty items, must be resurveyed and is subject to final approval from Insurance Company

Accident Date: 28.09.2020

Signature:

Date:

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

5 Days.

P/P

Refuse paint photos

Policy No: _____ Third Party

Date: 28.09.2020

Quo Qiamp

82880282

29/9/2020

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Renault Kadjar" Reg. No. SLP932J Claiming Against Your Insured Reg. No. SML6403P			
1pc	Front Door RH / BUC		1,850.00 1250
1pc	Front Door Sticker / MBL		375.00 40
1pc	Front Door Protector / SGR		440.00 220
10pcs	Front Door Protector Clips / MC	10.00	100.00 20
1pc	Front Door Protector Moulding / SGR		320.00 120
1pc	Front Door Insulation X NN		150.00
1pc	Front Door Weatherstrip X SGR		450.00
1pc	Front Door Lower Rubber X SGR		290.00
1pc	Front Door Tyre Pressure Sticker / SGR		25.00 15
9pcs	Front Door Inner Trim Board Clips / SGR	10.00	90.00 30
2pcs	Front Door Inner Trim Board Rivets / SGR	10.00	20.00 10
1pc	Rear Door Protector / SGR		420.00 210
10pcs	Rear Door Protector Clips / MC	10.00	100.00 20
1pc	Rear Door Protector Moulding / SGR		290.00 80
1pc	Front Fender Arch Protector / SGR		290.00 210
6pcs	Front Fender Arch Protector Clips / MC	10.00	60.00 20
1pc	Rear Fender Arch Protector / SGR		290.00 210
6pcs	Rear Fender Arch Protector Clips / MBL	10.00	60.00 20
			5,620.00 2475
	Less 10%		562.00
			5,058.00 2227.5
	To Dismantle / Transfer Front Door Fittings / Ancillary Accessories		60 150.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		RV X 60.00
	To Repair / Respray Rear Wheel Rim		50 100.00
	To Conduct Computerize Wheel Alignment Test		60 80.00
	Labour Charge - Panel Beating, Repairing Of Front Fender, Rear O/S Door, Rear Fender and Parts Replacement		400 600.00
	To Respray Affected Areas (Pearl)	1470	900 1,200.00
	Total :		<u>7,248.00</u>
			3697.5