

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Quotation No	Sep 004/2020
Date	25/9/2020
Vehicle No	SGP8758C
Make / Model	Suzuki Swift

Jaslin

2C113172293

To: AIG Asia Pacific Insurance Pte Ltd
Address: 78 Shenton Way #07-16 Singapore 079120

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	rear bumper <i>Dehd</i>		\$ 649.00 <i>549</i>
2 pcs	rear bumper side retainer <i>new LH</i>	\$ 65.00	\$ 130.00 <i>35</i>
1 pc	rear bumper lower spoiler <i>Dehd</i>		\$ 580.00 <i>380 (sw)</i>
1 pc	n/s rear door <i>Dehd</i>		\$ 795.00 <i>+</i>
1 pc	n/s tail lamp <i>new</i>		\$ 285.00 <i>+</i>
1 pc	n/s rear fender <i>Dehd</i>		\$ 397.00 <i>+</i>
1 pc	n/s rear sports rim <i>new</i>		\$ 580.00 <i>400 (sw)</i>
1 pc	n/s rear tyre <i>new</i>		\$ 250.00 <i>+</i>
1 pc	rear axle beam <i>new</i>		\$ 885.00 <i>+</i>
1 pc	n/s rear wheel bearing <i>new</i>		\$ 110.00 <i>+</i>
1 pc	n/s rear shock absorber <i>new</i>		\$ 230.00 <i>+</i>
1 pc	n/s side skirt <i>new</i>		\$ 680.00 <i>+</i>
1 pc	n/s rear fender inner shield <i>new</i>		\$ 95.00 <i>+</i>
1 set	n/s rear fender inner shield clip <i>new</i>		\$ 40.00 <i>+</i>
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair		\$ 1,000.00 <i>700</i>
2	to putty and spray painting on affected area		\$ 1,050.00 <i>800</i>
3	anti rust		\$ 100.00 <i>60</i>
4	wiring check		\$ 50.00 <i>30</i>
5	remove and refix cushion seat, carpet, looflining		\$ 120.00 <i>60</i>
6	remove and replace rear undercarriage		\$ 300.00 <i>60</i>
7	check and adjust wheel alignment		\$ 120.00 <i>80</i>
8	remove and refix fuel tank		\$ 180.00 <i>80</i>
9	transfer door <i>fitting</i>		\$ 120.00 <i>60</i>
	Subtotal:		\$ 8,746.00

BEST SOLUTION AUTOCARE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin Cj
2/5 29/09/20.
068up.

total: 4891.10

HS: 35K (Nett Value).

Authorised Signature