

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 20 October 2020 3:16 PM
To: 'Wai Yin Ng'
Subject: RE: TP VEHICLE SHD 296Y DOA: 26/09/2020 -- AAD2009-132

Dear Wai Yin,

Please ignore the email.

As spoken with you.

The repair cost should be Lump Sum \$1,600.00 instead of \$1,700.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 20 October 2020 3:00 PM
To: Wai Yin Ng <waiyin.ng@transcab.com.sg>
Subject: RE: TP VEHICLE SHD 296Y DOA: 26/09/2020 -- AAD2009-132

Dear Wai Yin,

WITHOUT PREJUDICE

Confirm Lump Sum \$1,700.00 before GST and 3 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wai Yin Ng <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 20 October 2020 2:53 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: TP VEHICLE SHD 296Y DOA: 26/09/2020 -- AAD2009-132

Without prejudice

Dear Shiau Chan

We propose the COR amount \$1,700.00 (before GST).

Please see my working below, kindly conform.

	AAD2009-132		
	SHD0296Y - DOA 26.09.20		
	PART	\$ 1,483.40	
		\$ 1,483.40	
	10%	\$ 148.34	
		\$ 1,335.06	
	S.NETT	\$ 80.00	
		\$ 80.00	
		\$ 160.00	
	LABOUR	\$ 200.00	
		\$ 400.00	
		\$ 600.00	
		\$ 2,095.06	
	LUMP SUM	\$ 1,676.05	

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Shiao Chan (LKKAUTO) [<mailto:siewsc@lkkauto.com>]
Sent: Tuesday, 20 October, 2020 2:44 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: TP VEHICLE SHD 296Y DOA: 26/09/2020

Dear Wai Yin,

Based on our surveyor's marking estimate, the calculation of repair cost will be at Lump Sum \$1,600.00 before GST and 3 repair days.

Kindly check and confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)