

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 53 Singapore 569111

Tel No. : 6287 6666

Fax No. : 6257 1330

CO./GST Reg. No. 2010196260

SHD 296Y

LKK Auto Consultants hence notify the Repairer of the following:

- Repair before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AAD2009-132

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 296Y

VF LABL15AUC282305

RENAULT

LATITUDE

26.9.2020

ERGO

4/3/2016

3 Days.
Impair Repair.
After repair.
29/9/2020.
Ema Qian
82880282.

PART		LIST	
1	FENDER PANEL FRT RH X repair.	\$	437.10
1	DOOR PANEL FRT RH X repair.	\$	2,844.66
1	DOOR MIRROR ASSY RH - D.S.	\$	1,483.40 ✓
1	DOOR MIRROR GLASS RH - Ants X	\$	242.33
1	DOOR MIRROR BACK COVER RH - Ants X	\$	218.46
1	DOOR MIRROR LAMP RH X	\$	194.18
1	DOOR FINISHER FRT RH X	\$	515.06
TOTAL		\$	5,935.19
10%		\$	593.52
		\$	5,341.67 1335.06

Special Nett

1	FRONT DOOR STICKER "Trans-Cab" - LMC.	\$	80.00	60
1	FRONT DOOR STICKER "Classic"	\$	80.00	15
TOTAL		\$	160.00	75

TOTAL PARTS \$ 5,501.67

LABOUR

To rust-proofing and apply undercoat of the affected areas

\$ 220.00 X MN

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 1,000.00 200

Putty and spray painting of the affected portion.

\$ 1,000.00 300 400

To Check Electrical Lighting Concerned.

\$ 170.00 X AN

600

2010.06

-20%: 1600

ans-cab Auto Services Pte Ltd

AAD2009-132

2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

UEN : S70000000/ GST Reg. No. 201019626G

Vehicle No. : 296Y

TOTAL \$ 2,390.00

Over All Total \$ 7,891.67

LUMP SUM (REPAIR DAY)

10 DAYS

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)