



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /CHUA DONG YANG Reg No/Reg Date SMD8103J / 06/09/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH003163 Engine No 3A92UHG6508 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	28/09/2020/ 16:44	BLC	442 / CocoLu	57828			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								5760.00
RENEW FRT BUMPER, FRT AIRDAM, BONNET, FRT SUPPORT PANEL,					(a 450 X 6 5			2250
FRT FENDER RH, SIDE SKIRT RH, FRT WHEEL HOUSING RH,								
REPAIR FRT FENDER LH, FRT DOOR RH, ROCKER PANEL RH, A-PILLAR RH								
E PNT88000								100.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								
E PNT88000								120.00
REMOVE & INSTALL FRT AIRDAM & SIDE AIRDAM								
M SUNDRY								80.00
TOP UP AIRCON GAS								
E PNT88000								240.00
REMOVE & INSTALL FRT WINDSCREEN (photo)								
M SUNDRY								80.00
APPLY SEALANT FOR FRT WINDSCREEN								
E PNT98000								4200.00
SPRAY PAINT FOR FRT BUMPER, FRT AIRDAM, FRT SUPPORT PANEL, BONNET					350 X 10			
FRT FENDER RH & LH, FRT DOOR RH, SIDE STILL RH, A-PILLAR RH,								
ROCKER PANEL RH, WHEEL HOUSING RH,								
A 54900099								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								30.00
TRANSFER FRT RIM TO TYRE								
54900099								675.00
REMOVE & INSTALL DASHBOARD TO FACILITATE REPAIR								
54900099								675.00
REMOVE & INSTALL ENGINE TO FACILITATE REPAIR photo?								
54900099								450.00
RENEW FRT UNDER CARRIAGE								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /CHUA DONG YANG Reg No/Reg Date SMD8103J / 06/09/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH003163 Engine No 3A92UHG6508 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim UO1 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	28/09/2020/ 16:44	BLC	442 / CocoLu	57828		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M SUNDRY							250 360.00
SUPPLY FRT TYRE							40.00
M SUNDRY							
APPLY SEALANT FOR ACCIDENT PORTION							
M	WHEELHOUSE,FR INR RH	buc	1.00	347.00	23.00		267.19
M	FACE,FR BUMPER	Token	1.00	703.00	23.00		541.31
M	MARK,THREE-DIA	X m	1.00	69.00	23.00		53.13
M	COVER,HEADLAMP SUPT PANEL	edh ? xsv	1.00	62.00	23.00		47.74
M	GRILLE,FR UNDER	ca	1.00	165.00	23.00		127.05
M	GARNISH,FR BUMPER,RH	ms	1.00	127.00	23.00		97.79
M	AIR DAM,SIDE,FR RH	? xsv	1.00	18.00	23.00		13.86
M	BRACKET,FR BUMPER,RH	? xsv	1.00	13.00	23.00		10.01
M	GRILLE,RADIATOR	X svt	1.00	554.00	23.00		426.58
M	LATCH,HOOD	X svt	1.00	69.00	23.00		53.13
M	HOOD	bt	1.00	734.00	23.00		565.18
M	HINGE,HOOD,RH	? xsv	1.00	56.00	23.00		43.12
M	INSULATOR,HOOD	ca	1.00	177.00	23.00		136.29
M	FENDER,FR RH	buc	1.00	497.00	23.00		382.69
M	SHIELD,FR WHEELHOUSE,RH	de	1.00	98.00	23.00		75.46
M	PANEL,HEADLAMP SUPPORT,UPR	bt xsv	1.00	65.00	23.00		50.05
M	PANEL ASSY,FR END	regt bt	1.00	1055.00	23.00		812.35
M	PANEL,AIR GUIDE,RH	? xsv	1.00	11.00	23.00		8.47
M	COVER,ENG ROOM UNDER,FR	? xsv	1.00	99.00	23.00		76.23
M	CLIP,HOOD LOCKING	? xsv	1.00	3.00	23.00		2.31
M	MOULDING,WINDSHIELD	Dec	1.00	100.00	23.00		77.00
M	STOPPER,WINDSHIELD GLASS	Dec	2.00	3.00	23.00		4.62
M	SPACER,WINDSHIELD	Dec	2.00	6.00	23.00		9.24
M	SPACER,QTR WINDOW	Dec	3.00	8.00	23.00		18.48
M	GARNISH,FR DECK	? xsv	1.00	178.00	23.00		137.06
M	GARNISH,FR PILLAR,RH	? xsv	1.00	30.00	23.00		23.10
M	GARNISH,FR FENDER	? xsv	1.00	65.00	23.00		50.05
M	BODY KIT ATTRAGE, TITANLUM GREY,U17	ca	1.00	1643.00	20.00	1643	1314.40
M	HEADLAMP ASSY,RH	ca	1.00	660.00	23.00		508.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<tr> <td>Cust No/Name</td><td>/CHUA DONG YANG</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMD8103J / 06/09/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AJH003163</td></tr> <tr> <td>Engine No</td><td>3A92UH66508</td></tr> <tr> <td>Make/Model</td><td>MIT/18MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>U01 TITANIUM GREY M/ BK BLACK</td></tr>	Cust No/Name	/CHUA DONG YANG	Reg No/Reg Date	SMD8103J / 06/09/201	Date In/Mileage	/ 0	Chassis No	MMBSTA13AJH003163	Engine No	3A92UH66508	Make/Model	MIT/18MY ATTRAGE 1.2 CVT	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK
Cust No/Name	/CHUA DONG YANG														
Reg No/Reg Date	SMD8103J / 06/09/201														
Date In/Mileage	/ 0														
Chassis No	MMBSTA13AJH003163														
Engine No	3A92UH66508														
Make/Model	MIT/18MY ATTRAGE 1.2 CVT														
Colour/Trim	U01 TITANIUM GREY M/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/09/2020/ 16:44	BLC	442 / CocoLu	57828

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M HEADLAMP ASSY, LH <i>con</i>	1.00	660.00	23.00	508.20
M LAMP ASSY, FOG, FR LH <i>X sue</i>	1.00	303.00	23.00	233.31
M TANK, WINDSHIELD WASHER <i>con</i>	1.00	74.00	23.00	56.98
M MOTOR, WINDSHIELD WASHER <i>dis</i>	1.00	30.00	23.00	23.10
M HUB ASSY, FR WHEEL <i>bt</i>	1.00	240.00	23.00	184.80
M BEARING, FR WHEEL HUB <i>ne</i>	1.00	121.00	23.00	93.17
M ARM ASSY, FR SUSP, LWR RH <i>bt</i>	1.00	337.00	23.00	259.49
M STRUT, FR SUSP <i>bt</i>	1.00	373.00	23.00	287.21
M BEARING, FR SUSP STRUT <i>ne</i>	1.00	9.00	23.00	6.93
M WHEEL, DISC <i>sea</i>	1.00	687.00	23.00	528.99

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Rasul - Hp 90010068SURVEYOR SIGNATURE: [Signature]DATE: 28/09/2020 @ 1710REMARKS: 12 daysREVERT / EXCESS: TBAPay before paint

Confirm & accepted by

23,934.33

7% GST on **Nett** 21175.02

21,175.02
1482.25

Total Payable

22,657.27

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SUPPLEMENTARY

INSURANCE CO : AIG ASIA PACIFIC INSURANCE PTE LTD

REGISTRATION NO : SMD8103J

S/N	Description	Qty	Unit Price	Disc%	Amount	
LABOUR						
1	RENEW FRONT CROSSMEMBER	1.00	225.00	0.00	225.00	✓
2	STRAIGHTEN FRONT CHASSIS - FLOOR BENCH	1.00	500.00	0.00	500.00	✓
3	REPAIR RH CHASSIS MEMBER	1.00	225.00	0.00	225.00	✓
PARTS						
1	CROSSMEMBER, FR AXLE, NO1 nec ✓	1.00	864.00	23.00	665.28	✓
2	LINK KIT, F/ SUSP STABILIZER bt ✓	1.00	27.00	23.00	20.79	✓
3	STOPPER, FR SUSP STRUT nec ✓	1.00	27.00	23.00	20.79	✓
4	KNUCKLE, RH bt ✓	1.00	365.00	23.00	281.05	✓
5	SNAP RING, FR WHEEL HUB nec ✓	1.00	8.00	23.00	6.16	✓
6	FRAME, FR DECK, UPR OTR RH bt ✓	1.00	511.00	23.00	393.47	✓
7	CABLE, HOOD LOCK RELEASE cut ✓	1.00	30.00	23.00	23.10	✓
8	COVER, HEADLAMP SUPT PANEL cra ✓	1.00	62.00	23.00	47.74	✓
9	CLIP, HOOD LOCKING nec ✓	1.00	4.00	23.00	3.08	✓
Total					2,411.46	
7 % GST					168.80	
Grand Total					2,580.26	

Thank You.

Yours faithfully,

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

JoJo Cheng

Customer Service

Tel : +65 6568 4554