NAME ADDRESS

Home Tel.:

VIN:

Registration: SKP 9301 H

Technician: Mileage:

Time Printed 30.9.20 6:29 PM

MAZDA 6

Front : Left

Actual	BEFORE	Specified Range
-0°47'		-1°18' 0°42'
6°02'		2°47' 4°47'
0°00'		-0°06' 0°17'
20°04'		
19°17'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Actual	BEFORE	Specified Range
4°23'		-1°18' 0°42'
6°09'		2°47' 4°47'
0°47'		-0°06' 0°17'
11°19'		
15°42'		

Front: Right

Front

Cross Camber Cross Caster Cross SAI Total Toe Cross Turn Diff.

Actual	BEFORE	Specified Range
-5°10'		-1°30' 1°30'
-0°07'		-1°30' 1°30'
8°45'		
0°47'		-0°11' 0°33'

Rear : Left

Actual	BEFORE	Specified Range
-1°04'		-2°13' -0°13'
-0°13'		-0°06' 0°17'

Camber

Actual	BEFORE	Specified Range
-1°34'		-2°13' -0°13'
0°18'		-0°06' 0°17'

Rear: Right

Rear

Cross Camber Total Toe Thrust Angle

Actual	BEFORE	Specified Range
0°30'		
0°05'		-0°11' 0°33'
-0°16'		-0°02' 0°02'

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACC	IDEN	IT S	TAT	EMENI	

28/09/2020 11:21 Date Of Report 26/09/2020 14:50 Date Of Accident

JURONG GATEWAY RD & JURONG EAST ST 21 JUNCTION Exact Location Of Accident

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

SKP9301H Vehicle Registration Number

Insured/Policyholder

WONG YUT MING Name Of Registered Owner

SXXXX752Z NRIC No NOEMAIL **Email Address**

(LOCAL) +65-86194018 Mobile Phone No OTHERS-86194018 Alternative Phone No

Vehicle Particulars

MAZDA Manufacturer

6-2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) Model

Exact Purpose for which vehicle was being used at PTE USE

time of accident

Are you claiming under your own insurance policy NO

for repair to your vehicle?

THIRD PARTY If No, Please state action to be taken

PRIVATE CAR Vehicle Category

Insurance Company

HL ASSURANCE PTE LTD Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

MP308311 Policy Number

21/10/2019 - 20/10/2020 Cover Note Number

Driver

YAP SHAN SHAN Name of Driver

SXXXX226I NRIC No 13/12/1970 Date Of Birth **INDOOR** Occupation 10/06/2004 Date Of Driving Pass

16 YEARS AND 3 MONTHS **Driving Experience**

FEMALE Gender

(LOCAL) +65-91150150 Mobile Number

Fax Number

Contact Number

SHAN2SPRING@YAHOO.COM.SG FMail Address

Address

BLK 319 CHOA CHU KANG AVE 3 #12-18

Postcode

689863

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

_

_

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

3

involved in the accident

YES

Was any body injured in the Accident?
Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

: DAVIAN WONG

GENDER:

: MALE

Passenger 2

NAME:

: SHIRLENE WONG

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes,Please state which Police Station

Police Station Name

CLEMENTI POLICE DIVISIONAL HQ (D DIVISION)

Police Station Address

ROAD: 20 CLEMENTI AVENUE 5 , **POSTCODE**: 129858 , **COUNTRY**: SINGAPORE

SINGAPORE

Police Station Contact

TEL NO: 1800-7740000 - FAX NO: 67741705

Was notice of intended Prosecution given? If Yes, against whom?

NO

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SMA5281M

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category

Name of Driver

Page 2 of 15

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKK1621M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name YAP SHAN SHAN

Approximate Age

Injuries Sustain

SORENESS OVER NECK, SHOULDER & LOWER BACK

Injured person in which vehicle? SKP9301H

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

NO

Address Postcode

DETAILS OF INJURED PERSON 2

Name WONG KAI JIE DAVIAN, T0724050Z

Approximate Age

Injuries Sustain

BUMPED HIS HEAD AGAINST THE ROOF

Injured person in which vehicle? SKP9301H

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

YES

Address

Postcode

DETAILS OF INJURED PERSON 3

Name WONG WAI TENG SHIRLENE, S9932825H

Approximate Age

Injuries Sustain KNOCK ON RIGHT KNEE

Injured person in which vehicle? SKP9301H

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- SKP 93014 (HL) Do Ac 26/09/20 @ 1450
- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder)

Date & Time: > 09 | 2000

Reporting Centre Personnel's Signature

NRIC/FINNO ... YV MINE OF

Sketch Plan #2

SKETCH PLAN			
↑ → ¬ ¬ ← ←	& Junong East Street 21 Junction	Jump Genteucy 24 4 12 4	Vehicle A - SKP9301H Vehicle B - SMA5281M Vchicle C - SKK1621M
ESCRIBE CIRCUMSTA	NCES OF THE ACCIDENT VENICLE	No: SKP 931	014 (41)
on the	stated date and time, 1,	vehicle A (Skp	9301H) was travelling
collided onto the	the stated location. Suddenly, veh front right portion of my vehicle, vicle ((SKK1621M) from the opposite pairing My rehicle at 21166 1m	then ended up m	louting the Kerb and
DECLARATION /We declare the foregoing	particulars are true in every respect.		
to a marier a sile rai abouile	Churt		A
Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder) Date & Time: 28/09/2020		mtre Personnel's Signature

Date & Time: 28/09/2020

Page 5 of 15

Sketch Plan #3





1 of 2

POLICE REPORT (NP299)

Police Station Of Origin Clementi Division HQ 20 Clementi Avenue 5 SINGAPORE 129858 Tel No:1800-7740000 Report No. D/20200927/7018

Date/Time Report Made 27/09/2020 17:42	Vide Rep	ort No.		Station Diary No.
Name Of Informant YAP SHAN SHAN	Address 319 CHO 689863	A CHU KA	NG AVE 3 #12-18	3 SINGAPORE
ID Type / ID No. NRIC NO / S7043226I	Contact N Home/Off		Mobile: 91150150	
Nationality SINGAPORE CITIZEN	Email Add		AHOO.COM.SG	
Occupation BUSINESS ANALYST	Sex Female	Age 49	Date of Birth 13/12/1970	Race Chinese
Institution/School Name	Language English)		
Date/Time Of Incident 26/09/2020 14:50		Location Of Incident JURONG GATEWAY ROAD		
Brief details.				

Vide D/20200926/0075

On the above mentioned date and time, I was driving my vehicle SKP 9301H with my son and daughter on board.

I was travelling along Jurong Gateway Road towards Toh Guan Road.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 27/09/2020 17:42
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

Sketch Plan #4





2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. D/20200927/7018

As I was approaching the junction of Jurong Gateway Road and Jurong East Street 21, I had slowed down a little to keep a lookout and continued cruising ahead after realising that traffic was clear and traffic light was in my favour.

Just as I had passed the said cross junction, travelling along e middle of 3 lanes, I felt a huge impact from the front right portion of my vehicle. Impact was so huge that my vehicle got bumped into the lane on my left.

I alighted to realise that SMA 5281M had crashed into the front right portion of my vehicle. SMA 5281M subsequently collided into the barrier and into another vehicle, SKK1621M, on the opposite side of the road.

My son, Wong Kai Jie Davian, T0724050Z, was sitting right behind me bumped his head against the roof. My daughter, Wong Wai Teng Shirlene, S9932825H, suffered a knock on her right knee.

Initially, I was fine but later that evening, I started to feel soreness over my neck, shoulder and lower back regions.

I brought my son to our family doctor at CCK FAMILY CLINIC for treatment. We were both given 4 days MC.

My daughter went to the same clinic the next morning and was given 5 days MC.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by
	SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 27/09/2020 17:42
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Skip Pentatonics - Do This

Pentatonic Scales Make The Guitar Puzzle Here's Why



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Advertiser Login Ways of Selling




WOW! 2.5% P.A, \$438 Monthly By Gv Financing, \$0 Admin,\$0 Down,2 years warranty StarAd



Lake View & Credit Pte Ltd

view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable





Mazda CX3 2.0A Brand New (For Lease)

\$1,950/mth Brand New Mazda CX3 2.0A (White) available For Lease. Please contact Jeannie at 9786 7033 for more info.

More info about this vehicle



Mazda 6 2.0A Executive

\$10,150 /vr \$63,900

31-Dec-2015

1,998 cc

100,000 km

Luxury

Available

Sporty Pearl Soul Red! Agent Serviced! 100% Genuine Low KM With Records To Prove! Not Clocking Back Oedometer PHV For Sure! High Specs Exec Model With DRL, HeadUp Display, Memory Seats, Nav, Istart Stop, Seat With Lumber Control For Long Dist Drive! Walk Awa...

Posted: 13-Sep-2020 Tags: 2015 Mazda 6, Mazda 6, Mazda, 6

Save this search criteria, to get email alerts whenever a match is found.

B Save Search























JWG INTERNATIONAL PTE. I

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOLIK Auto Consultants hence notify

H/P: 9698 8882 | FAX: 6484 1922 E-Mail: jwg.claims@yahoo.com

CHINA TAIPING To:

MOTOR CLAIMS DEPARTMENT Att:

To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

ACCIDENT INVOLVING SKP9301H [OUR CLIENT] & SMA528TM [YOUR INSURED] ON 26/09/2020.

ESTIMATED REPAIR COSTS FOR SKP9301H

AMOUNT PARTS **OTY**

1PC	FRONT BUMPER TOTAL	1151.30	\$_	1,396.00
1SET	FRONT BUMPER CLIPS Nec 17:70		\$	35.00
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$78.00 EACH	SKH HSH	\$	35.00 156.00
1PC	FRONT BUMPER SENSORS WIRE HARNESS ASSY. 2 ton	1	\$	296.00
1PC	FRONT BUMPER FOGLAMP ASSY. HF		\$	663.00
1PC	FRONT BUMPER FOGLAMP COVER		\$	77.00
1PC	FRONT BUMPER LOWER GRILLE		\$	278.00
1SET	FRONT BUMPER LOWER GRILLE CLIPS		\$	20.00
1PC	FRONT RH FENDER 3nc	383.70	\$	658.00
1PC	FRONT RH FENDER SHIELD		\$	115.00
1SET	FRONT RH FENDER SHIELD CLIPS Have		\$	18.00
1PC	FRONT HEADLAMP RH Joken		_	2,378.00
1PC	FRONT HEADLAMP RH BRACKET AND		\$	98.00
1PC	FRONT RH ABSORBER & author		\$	460.00
1PC	FRONT RH ABSORBER MOUNTING	120	\$	95.00
1PC	FRONT RH ABSORBER DUST COVER HU		\$	49.00
1PC	FRONT RH ABSORBER STOPPER		\$	46.00
1PC	FRONT RH TIE ROD HAN & HAN		\$	238.00
1PC	FRONT RH TIE ROD END		\$	249.00
1PC	FRONT RH STEERING RACK ASSY. 144		_	1,161.00
1PC	FRONT STABILZER BAR		\$	422.00
1PC	FRONT RH STABILIZER LINK	* 44	\$	116.00
1PC	FRONT RH KNUCKLE ARM A disturb	387.70	\$	502. 00
1PC	FRONT RH LOWER ARM * Mystush	246.00	\$	554.00
1PC	FRONT RH WHEEL BEARING & HUB ASSY. 🗷 Daw	539.70	\$	668.00
1PC	FRONT RH DRIVE SHAFT ASSY.		_	1,897.00
1PC	FRONT RH SIDE MIRROR		\$	787.00
1PC	FRONT SUPPORT PANEL & CYCL	699.00		1,096.00
1PC	FRONT REINFORCEMENT BAR 以		\$	613.00
1PC	FRONT REINFORCEMENT SPONGE		\$	329.00

1PC	FRONT GRILLE mounty boles		\$	517.00	ダレ
1SET	FRONT GRILLE CLIPS		\$	25.00	1
1PC	FRONT GRILLE CHROME 2 wt		\$	319.00	1
1PC	FRONT GRILLE INNER LOWER GARNISH Z ~~		\$	179.00	X
1PC	FRONT WASHER TANK broken	188.50	\$	378.00	-
1PC	FRONT WASHER TANK MOTOR Deve	159.00	\$	2 98.0 0	1
1PC	FRONT WASHER TANK FILLER PIPE HA		\$	109.00	X
1PC	FFRONT WASHER TANK FILLER PIPE BRACKET		\$	67.00	7
1PC	FRONT ENGINE UNDERCOVER Z Clark		\$	274.00	10
1SET	FRONT ENGINE UNDERCOVER CLIPS ? ~ Lc		\$	20.00	20
1PC	FRONT BONNET Dendal	1204.00	\$	1,723.00	1
2PCS	FRONT BONNET HINGE LH / RH @ \$108.00 EACH		\$	216.00	X
		DARTS SIIM.	\$ 1	9 595 00	

8098.88

PARTS SUM: \$ 19,595.00 PARTS LESS 20%: \$ 3,919.00 PARTS TOTAL: \$ 15,676.00

LABOUR & SPECIAL NETT ITEMS

* *	TO SUPPLY 1PC FRONT RH TYRE TO SUPPLY 1 SET FRONT SENSOLS \$500.00 220 - Dev TO SUPPLY 1PC FRONT RH BRANDED SPORTS RIM SH 720. Weut	\$ \$ \$	400.00 X H SH 1,800.00 500 -
*	TO REMOVE & REFIT FRONT RH DAMAGED UNDER CARRIAGE PARTS	\$	500.00 150/
*	TO CONDUCT COMPUTERIZE 4-WHEELED ALIGNMENT TEST	\$	180.00 66 -
*	TO ROTATE & BALANCE FRONT RH TYRE	\$	100.00 20 -
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$	1,800.00 800 -
*	TO RESPRAY NEW PAINTWORK ALL DAMAGED AREAS	\$	1,800.00 800 -
*	TO REFIT NEW FRONT BUMPER SENSORS ON NEW FRONT BUMPER	\$	180.00 40 -
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS 1940.00	\$	200.00 30 -
*	TO COMPUTERIZED REFOCUS FRONT HEADLAMP BEAM	\$	120.00
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$	300.00 HM
*	TO APPLY ANTI-RUST COATINGS ON ALL AFFECTED AREAS	\$	300.00 40

LABOUR & S/N TOTAL: \$ 7,680.00

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592 E-Mail: jwg.claims@yahoo.com

To: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SMA5281M [YOUR INSURED] & SKP9301H [OUR CLIENT] ON 26/09/2020.

SUPPLYMENTARY ITEMS FOR SKP9301H

QTY	<u>PARTS</u>		AMOUNT		
1PC	FRONT FENDER BRACKET RH 154	\$	422.98		
1PC	FRONT ENGINE UNDERCOVER LOWER Stymul	\$	257.75		

PARTS SUM: \$

680.73

PARTS LESS 20%: \$

136.15

PARTS TOTAL: \$

544.58

GRAND TOTAL SUPPLEMENTARY ITEMS: \$

544.58

JEK Aud

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

23900:58