

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0707/2020/NS
DATE : 29-Sep-20
WIP : 51159

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SMP 9347 C

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS PATSY WONG PEI SZE
ADDRESS : BLK 28 MARINE CRESCENT
#03-11
SINGAPORE 440028
TELEPHONE : HP +65 91739175
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5103591818-01
VEHICLE NO : **SFL 3328 B**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 24/8/2016
ENGINE NO : CVN 014938
CHASSIS NO : WAUZZZF48GA111604
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Sep-20
PLACE OF ACCIDENT : MARINE CRESCENT CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFL 3328 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORHANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	
4	TO RESPRAY FRONT BUMPER	\$ 900.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: <u>\$ 2,772.00</u>	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFL 3328 B

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 2,111.00	
2	FRONT BUMPER FIXING PARTS		\$ 282.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 70.00	
4	FRONT BUMPER GRILLE - CENTRE		\$ 194.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 208.00	
6	RADIATOR GRILLE		\$ 1,799.00	
7	FRONT BUMPER AIR GUIDE GRILLE - LH		\$ 361.00	
8	FRONT BUMPER CARRIER		\$ 795.00	
9	FRONT BUMPER FOAM FILLER PIECE		\$ 123.00	
10	FRONT BUMPER TOP COVER		\$ 126.00	
11	CAUTION SIGN STICKER	NEC	\$ 14.00	
12	AIRCON STICKER	NEC	\$ 8.00	
13	LOCK CARRIER BRACKET		\$ 136.00	
14	LOCK CARRIER BRACKET SUPPORT - H / RH	2	\$ 56.00	
15	LED HEADLIGHT - LH		\$ 7,693.00	
16	LIFT CYLINDER - LH		\$ 208.00	
17	FRONT NO PLATE	S/N	\$ 60.00	
18	SUNDRIES		\$ 200.00	
TOTAL SPARE PARTS		:	\$ 14,444.00	
TOTAL LABOUR CHARGES		:	\$ 2,772.00	
GRAND TOTAL		:	\$ 17,216.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT