

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 519E**AAD2009-139***1/Sng @ 16,400hr*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

29 SEP 2020**SHD 519E**

VF1ABL15AUC283438

RENAULT

LATITUDE

24.9.2020

AIG

17/11/2017

PART**LIST**

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER REFLECTOR RH
- 1 BUMPER BRACKET SIDE LH REAR
- 1 BUMPER RETAINER LH REAR
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET RH REAR
- 1 BUMPER HARNESS REAR
- 1 OUTER PANEL REAR (End Panel)
- 1 OUTER PANEL REAR (End Panel) TRIM
- 1 TAILLAMP RH
- 1 TAILLAMP PANEL RH
- 1 BOOT REAR
- 1 BOOT FINISHER
- 1 BOOT WEATHERSTRIP
- 1 BOOT REFLECTOR LAMP RH
- 1 BOOT BADGE 'RENAULT'
- 1 BOOT BADGE
- 1 BOOT TRIM BOARD
- 1 BOOT STRUT
- 1 BOOT HINGE RH
- 1 EXHAUST REAR
- 1 EXHAUST CAP REAR

\$	<i>Sn</i>	561.70	✓
\$	<i>Dis/In</i>	411.90	✓
\$	<i>Sn</i>	98.10	X
\$	<i>CM</i>	82.10	✓
\$	<i>CM</i>	59.80	✓
\$	<i>Bn</i>	16.60	✓
\$	<i>Sn</i>	80.80	X
\$	<i>Sn</i>	54.20	X
\$	<i>Bn</i>	547.80	✓
\$	<i>R</i>	114.50	X
\$	<i>Sn</i>	301.10	X
\$	<i>Bn</i>	745.80	✓
\$	<i>CM</i>	404.56	✓
\$	<i>Bn</i>	401.40	✓
\$	<i>Bn</i>	401.40	✓
\$	<i>Bn</i>	1,677.20	✓
\$	<i>Sn</i>	344.70	X
\$	<i>Dis/In</i>	178.20	✓
\$	<i>CM</i>	277.70	✓
\$	<i>Rn</i>	82.40	✓
\$	<i>Rn</i>	95.80	✓
\$	<i>Sn</i>	611.00	X
\$	<i>Sn</i>	145.10	X
\$	<i>R</i>	254.20	X
\$	<i>Bn</i>	5,263.60	<i>3200sn</i>
\$	<i>Bn</i>	125.40	✓

Trans-cab Auto Services Pte Ltd

AAD2009-139

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 519E

1 FENDER PANEL REAR RH	\$	B ₁ 1,933.20	✓
1 WHEELARCH REAR RH	\$	cm 275.40	✓
1 FENDER PANEL INNER TRIM REAR RH	\$	De form 671.45	✓
1 SPARE WHEEL PANEL	\$	n 1,229.40	X
1 SPARE WHEEL PANEL TRIM	\$	sn 612.21	X
1 SPARE TYRE BOARD	\$	sn 680.90	X
1 CHASSIS PANEL REAR RH	\$	R 2,192.40	X
1 FENDER PANEL INNER REAR RH	\$	B ₁ 1,241.60	✓
1 FENDER INNER BOARD RH	\$	sn 561.40	X
1 FENDER WHEEL HOUSING PANEL REAR RH	\$	n 4,682.09	
1 KNUCKLE ARM REAR RH	\$	sn 472.10	
1 WHEEL HUB NUT	\$	sn 41.80	
1 WHEEL HUB CAP	\$	sn 30.50	
1 REAR AXLE	\$	sn 3,469.00	
1 AXLE SPRING ARM RH	\$	sn 220.60	
1 UPPER CONTROL ARM REAR RH	\$	sn 543.50	
1 ABSORBER REAR	\$	sn 217.30	
1 STABILIZER BAR REAR	\$	sn 427.90	
1 STABILIZER LINK REAR	\$	sn 55.20	
1 SUBFRAME ARM REAR RH	\$	sn 198.33	
1 RODE - LONG REAR RH	\$	sn 120.16	
1 KNUCKLE HUB+BEARING RH	\$	sn 272.30	
1 DOOR PANEL REAR RH	\$	n 2,844.66	
1 DOOR LOCK REAR RH	\$	n 467.30	
1 DOOR FINISHER REAR RH	\$	sn 230.30	
TOTAL	\$	37,028.06	
10%	\$	3,702.81	
	\$	33,325.25	

Special Nett

1SET PARKING AID	\$	Tn 700.00	400.00
1SET REAR BUMPER CLIP	\$	na 90.00	75.00 ✓
1SET BUMPER BRACKET CTR CLIP	\$	na 65.00	X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 65.00	X

Trans-cab Auto Services Pte Ltd

AAD2009-139

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 519E

1SET BUMPER RETAINER RH CLIP RR	\$	na	60.00	X
1SET BUMPER LOWER REAR RIVET	\$	na	80.00	65na
1SET BUMPER LOWER REAR CLIP	\$	na	90.00	X
1 BOOT STICKER "Trans-cab"	\$	na	80.00	30na
1 BOOT STICKER "6555-3333"	\$	na	80.00	30na
1SET BOOT FINISHER CLIP	\$	na	60.00	X
1 TAILLAMP CLIP	\$	na	55.00	15na
1 Rear Bumper Protector	\$	na	180.00	X
1 REAR LICENCE PLATE WITH HOLDER	\$	na	130.00	X
1 FENDER INNER TRIM CLIP RH	\$	na	65.00	X
1SET FENDER WHEELARCH REAR RH CLIP	\$	na	75.00	X
2 REAR WINDSCREEN SEALANT	\$	na	150.00	40na
1 WINDSCREEN MOULDING	\$	na	200.00	X
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	30na
2 SEAM SEALANT	\$	na	170.00	X
1 RENAULT TYRE 215/60/16	\$	na	330.00	X
1 RENAULT TYRE RIM	\$	na	380.00	✓
1SET END PANEL TRIM CLIP	\$	na	60.00	X
1 BOOT TRIM BOARD CLIP	\$	na	60.00	X
1 EXHAUST MOUNTING	\$	na	60.00	X
1 EXHAUST BRACKET REAR	\$	na	55.00	X
1 REAR DOOR STICKER "6555-3333"	\$	na	100.00	X
TOTAL	\$		3,570.00	

TOTAL PARTS	\$	36,895.25
--------------------	-----------	------------------

LABOUR

Towing Fees	\$	150.00	501
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	18001
To transfer of tire, rim and on wheel balancing.	\$	170.00	201

Trans-cab Auto Services Pte Ltd

AAD2009-139

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 519E

To check steering geometry and computer wheel alignment	\$	220.00	601
To drop rear exhaust box, renew the same, to repair and realign rear and centre exhaust pipe.	\$	250.00	801
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	901
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1201
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 250.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	1201
To dismantle and refit rear undercarriage and axle assy, removal and renewal of parts, final checking and testing.	\$	nn 480.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	400.00	2501
To Check Electrical Lighting Concerned.	\$	170.00	201
To reinstall rear bumper parking sensor.	\$	170.00	601

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 519E

AAD2009-139

To check ABS and brake efficiency, final checking and testing.	\$	380.00	X
Putty and spray painting of the affected portion.	\$	2,000.00	13201
To repair and realign rear exhaust pipe.	\$	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
TOTAL	\$	8,540.00	
Over All Total	\$	45,435.25	

PART BY PART (REPAIR DAY)

25 DAYS

14 days

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 519E**AAD2009-139***Not Notified
Recovery Beparing*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 519E

VF1ABL15AUC283438

RENAULT

LATITUDE

24.9.2020

AIG

17/11/2017

*2 1/2 days***SUPPLEMENTARY ESTIMATE**

PART		LIST
1 BUMPER COVER FRT	\$	CM 747.20 ✓
1 BUMPER GRILLE LOWER FRT	\$	SL 147.00 X
1 BUMPER SPOILER FRT	\$	SL 344.70 X
1 BUMPER RETAINER FRT LH	\$	SL 101.40 X
1 BUMPER RETAINER FRT RH	\$	SL 101.40 X
1 RADIATOR GRILLE	\$	RM 969.90 ✓
1 RADIATOR GRILLE FRAME	\$	CM 686.00 ✓
1 BUMPER FOG LAMP GRILLE LH	\$	SL 207.21 X
1 BUMPER ABSORBER FRT	\$	SL 394.68 X

TOTAL	\$	3,699.49
10%	\$	369.95
	\$	3,329.54

Special Nett

1 BUMPER CLIP FRT	\$	RM 85.00 66.50
1 BUMPER RETAINER CLIP FRT	\$	RM 70.00 X
1 BUMPER GRILLE LOWER CLIP	\$	RM 70.00 X
1 BUMPER FOG LAMP GRILLE CLIP	\$	RM 65.00 X
1 BUMPER SPOILER CLIP	\$	RM 65.00 X
1 BUMPER BRACKET CLIP	\$	RM 75.00 X
1 SET Front licence plate with holder	\$	RM 120.00 45.50

Trans-cab Auto Services Pte Ltd**AAD2009-139**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 519E

TOTAL	\$	550.00
--------------	-----------	---------------

TOTAL PARTS	\$	3,879.54
--------------------	-----------	-----------------

LABOUR

Putty and spray painting of the affected portion.

\$	1,400.00	2201
----	----------	------

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	1,200.00	304
----	----------	-----

To Remove and Refit Of Bumper Fittings, Attachments And Perform Water Seepage Test.

\$	170.00	22 X
----	--------	------

TOTAL	\$	2,770.00
--------------	-----------	-----------------

Over All Total	\$	6,649.54
-----------------------	-----------	-----------------