

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0711/2020/NS
DATE	:	30-Sep-20
WIP	:	51280

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.
YOUR INSURED VEH NO : SLX 365 D

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR THAI SHIEN CHURN SAM
ADDRESS	:	BLK 200A SENGKANG EAST ROAD #15-10 SINGAPORE 541200
TELEPHONE	:	HP +65 98330773
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	10791119
VEHICLE NO	:	SLN 7699 Y
MODEL CODE	:	AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR	:	17/5/2017
ENGINE NO	:	CVN 034021
CHASSIS NO	:	WAUZZZF45HA129155
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	14-Sep-20
PLACE OF ACCIDENT	:	325B SENGKANG E WAY

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 7699 Y**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00 ✓	
2	TO DISMANLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00 500	
3	TO RESPRAY REAR BUMPER.	\$ 900.00 550	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 2,502.00</u>	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 7699 Y

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER <i>Rep's</i>		\$	2,181.00	+
2	REAR BUMPER FIXING PARTS		\$	72.00	+
3	REAR BUMPER SECURING STRIP		\$	220.00	+
4	REAR BUMPER SPOILER		\$	246.00	+
5	REAR LIGHT REFLECTOR - LH / RH	2	\$	82.00	+
6	REAR BUMPER CARRIER		\$	886.00	+
7	REAR BUMPER CARRIER SEAL	2	\$	28.00	+
8	REAR BUMPER GUIDE SECTION - LH / RH	2	\$	44.00	+
9	REAR PARKING AID SENSOR - INNER / OUTER	2		TBC	+
10	REAR PARKING AID SEAL RING	4	\$	14.00	+
11	SUNDRIES		\$	200.00	+
TOTAL SPARE PARTS		:	\$	3,973.00	
TOTAL LABOUR CHARGES		:	\$	2,502.00	
GRAND TOTAL		:	\$	6,475.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian G*
SURVEYED DATE : *01/10/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT