



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0695/2020/NS
DATE : 26-Sep-20
WIP : 50782

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

3 days ok - 02/12/2020 - Carrine

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR JIN LI
ADDRESS : BLK 339 CHOA CHU KANG AVE 3
#09-17
SINGAPORE 689873
TELEPHONE : HP +65 96254929
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070125093
VEHICLE NO : SKP 8396 R
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 26/8/2020
ENGINE NO : DKY 005146
CHASSIS NO : WAUZZZF28LN030104
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Sep-20
PLACE OF ACCIDENT : ROSEWOOD DRIVE OUTSIDE ESSO PETROL STATION



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKP 8396 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$ 280.00	\$ 280.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N	\$ 400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 800.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER		\$ 1,100.00	\$ 550.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 2,772.00	\$ 1,522.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKP 8396 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 2,763.00	
2	FRONT BUMPER FIXING PARTS		\$ 643.00	
3	FRONT BUMPER CLOSING ELEMENT - CENTRE		\$ 220.00	
4	FRONT BUMPER ADAPTER - LH		\$ 39.00	\$ 30.88
5	FRONT BUMPER REINFORCEMENT BRACKET - LH		\$ 110.00	
6	FRONT BUMPER GRILLE - LOWER CENTRE		\$ 151.00	
7	FRONT BUMPER CLOSING ELEMENT - LOWER		\$ 208.00	\$ 166.00
8	FRONT BUMPER SPOILER		\$ 249.00	
9	FRONT BUMPER AIR GUIDE GRILLE - LH		\$ 429.00	
10	FRONT BUMPER SIDE AIR GUIDE - LH LOWER		\$ 28.00	
11	FRONT BUMPER SIDE AIR GUIDE - LH UPPER		\$ 21.00	
12	RADIATOR GRILLE		\$ 2,192.00	\$ 1,753.60
13	RADIATOR GRILLE COVER		\$ 54.00	
14	RADIATOR GRILLE COVER CAP		\$ 88.00	
15	RADIATOR GRILLE BRACKET		\$ 92.00	
16	FRONT BUMPER CARRIER		\$ 960.00	
17	FRONT BUMPER SUPPORT	2	\$ 59.00	
18	FRONT BUMPER GUIDE SECTION - LH		\$ 44.00	
19	FRONT BUMPER BRACKET - LH		\$ 54.00	
20	FRONT BUMPER COVER		\$ 124.00	
SUB-TOTAL SPARE PARTS		:	\$ 8,528.00	\$ 1,950.48

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKP 8396 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 1,950.48
21	FRONT BUMPER FOAM FILLER PIECE		\$ 223.00	
22	CAUTION SIGN STICKER	NEC	\$ 14.00	
23	HORN - LH LOW TONE		\$ 214.00	
24	SPRING SHACKLE - LH		\$ 47.00	
25	FRONT PARKING AID SENSOR	2	TBC	
26	FRONT PARKING AID SEAL RING	4	\$ 14.00	
27	WHEEL SPOILER - LH		\$ 164.00	
28	HEADLIGHT MOUNTING - LH		\$ 117.00	
29	LED HEADLIGHT - LH		\$ 8,432.00	
30	LIFT CYLINDER - LH		\$ 196.00	
31	RADIATOR AIR GUIDE - LH		\$ 38.00	
32	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
33	SUNDRIES		\$ 200.00	
TOTAL SPARE PARTS		:	\$ 18,247.00	\$ 2,010.48
TOTAL LABOUR CHARGES		:	\$ 2,772.00	\$ 1,522.00
GRAND TOTAL		:	\$ 21,019.00	\$ 3,532.48

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-27/11/20