

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0695/2020/NS
DATE : 26-Sep-20
WIP : 50782

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR JIN LI
ADDRESS : BLK 339 CHOA CHU KANG AVE 3
#09-17
SINGAPORE 689873
TELEPHONE : HP +65 96254929
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070125093
VEHICLE NO : **SKP 8396 R**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 26/8/2020
ENGINE NO : DKY 005146
CHASSIS NO : WAUZZZF28LN030104
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Sep-20
PLACE OF ACCIDENT : ROSEWOOD DRIVE OUTSIDE ESSO PETROL STATION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKP 8396 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$ 280.00 ✓	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N	\$ 400.00 X.	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 800.00 500 ✓	✓
4	TO RESPRAY FRONT BUMPER		\$ 1,100.00 550 ✓	✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		:	<u><u>\$ 2,772.00</u></u>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKP 8396 R

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	\$	2,763.00	+
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$	643.00	+
3	FRONT BUMPER CLOSING ELEMENT - CENTRE <i>new</i>	\$	220.00	+
4	FRONT BUMPER ADAPTER - LH <i>2 cancelled</i>	\$	39.00	✓ 30.88
5	FRONT BUMPER REINFORCEMENT BRACKET - LH <i>new</i>	\$	110.00	+
6	FRONT BUMPER GRILLE - LOWER CENTRE <i>2 new</i>	\$	151.00	+
7	FRONT BUMPER CLOSING ELEMENT - LOWER <i>1 new</i>	\$	208.00	✓ 166
8	FRONT BUMPER SPOILER <i>new</i>	\$	249.00	+
9	FRONT BUMPER AIR GUIDE GRILLE - LH <i>cut</i>	\$	429.00	✓ X NN
10	FRONT BUMPER SIDE AIR GUIDE - LH LOWER <i>new</i>	\$	28.00	+
11	FRONT BUMPER SIDE AIR GUIDE - LH UPPER <i>new</i>	\$	21.00	+
12	RADIATOR GRILLE <i>cut</i>	\$	2,192.00	✓ 1753.60
13	RADIATOR GRILLE COVER	\$	54.00	+
14	RADIATOR GRILLE COVER CAP	\$	88.00	+
15	RADIATOR GRILLE BRACKET	\$	92.00	+
16	FRONT BUMPER CARRIER	\$	960.00	+
17	FRONT BUMPER SUPPORT	2 \$	59.00	+
18	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	\$	44.00	+
19	FRONT BUMPER BRACKET - LH <i>new</i>	\$	54.00	+
20	FRONT BUMPER COVER <i>new</i>	\$	124.00	+
SUB-TOTAL SPARE PARTS		:	\$ 8,528.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKP 8396 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 FRONT BUMPER FOAM FILLER PIECE <i>Not nec</i>		\$ 223.00	<i>+</i>
22 CAUTION SIGN STICKER <i>2</i>	NEC	\$ 14.00	<i>+</i>
23 HORN - LH LOW TONE <i>Not nec</i>		\$ 214.00	<i>+</i>
24 SPRING SHACKLE - LH <i>nec</i>		\$ 47.00	<i>+</i>
25 FRONT PARKING AID SENSOR <i>2</i>	2	TBC	<i>+</i>
26 FRONT PARKING AID SEAL RING <i>4</i>	4	\$ 14.00	<i>+</i>
27 WHEEL SPOILER - LH <i>Not nec</i>		\$ 164.00	<i>+</i>
28 HEADLIGHT MOUNTING - LH <i>Not nec</i>		\$ 117.00	<i>+</i>
29 LED HEADLIGHT - LH <i>Not nec</i>		\$ 8,432.00	<i>+</i>
30 LIFT CYLINDER - LH <i>2</i>		\$ 196.00	<i>+</i>
31 RADIATOR AIR GUIDE - LH <i>Not nec</i>		\$ 38.00	<i>+</i>
32 FRONT NO PLATE <i>nec</i>	S/N	\$ 60.00	<i>✓</i>
33 SUNDRIES <i>Not nec</i>		\$ 200.00	<i>?</i>
TOTAL SPARE PARTS	:	\$ 18,247.00	
TOTAL LABOUR CHARGES	:	\$ 2,772.00	
GRAND TOTAL	:	\$ 21,019.00	<i>✗</i>

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *29/09/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT