

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Yong, Joanne

Date: 30 Sep 2020

Preliminary Advice

Vehicle No	: SKP8396R	Accident Date	: 24/09/2020
Make	: AUDI A6	Policy No.	: 2070125093
Assignment Date	: 30/09/2020	Excess	: S\$0.00
Date of Inspection	: 29/09/2020	Est. Duration of Repair	: 3
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,019.00
Revised Amount	:S\$	4,203.00
Check Items (Estimated)	:S\$	200.00
Total	:S\$	4,403.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	165,000.00
COE / PARF Rebate	:S\$	77,823.00
Salvage Value	:S\$	
Margin for Repair	:S\$	87,177.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :