

Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 4179

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : GBK3226P

Accident Date : 28/9/20

Location : SLE TOWARDS CITY BEFORE EXIT 5

TPChin.
XiaoChen

Model:

NISSAN NV200

(30/3/2020)

3P: GBF2080A (China Taiping)

VSKYBAM2040179071

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>del</i>	-	-	695.90
2	2pcs	Rear bumper o/s & n/s retainer <i>m</i>	-	-	86.60
3	10 pcs	Rear bumper clips <i>m</i>	-	30.00	-
4	1 pc	Rear bumper sponge <i>cut</i>	-	-	80.20
5	2pcs	Rear bumper o/s & n/s reflector <i>LN missing</i>	-	-	86.60
6	1 pc	Rear n/s tail-lamp <i>cut</i>	-	-	365.20
7	1 pc	Rear o/s & n/s tail-lamp inner seal <i>new</i>	-	-	10.00
8	1 pc	Rear o/s tail-gate <i>Del</i>	-	-	1,057.00
9	1 pc	Rear o/s tail-gate weatherstrip <i>new</i>	-	-	215.00
10	1 pc	Rear o/s tail-gate lock <i>new</i>	-	-	215.50
11	1 pc	Rear o/s tail-gate lock catch <i>new</i>	-	-	63.60
12	1 pc	Rear o/s windscreen moulding <i>m</i>	-	-	130.00
13	1 pc	Rear n/s tail-gate <i>Dist</i>	-	-	1,409.20
14	1 pc	Rear n/s tail-gate inner board <i>Del</i>	-	-	180.00
15	12pcs	Rear n/s tail-gate inner board clips <i>m</i>	-	36.00	-
16	1 pc	Rear n/s tail-gate garnish <i>del</i>	-	-	143.00
17	4 pcs	Rear n/s tail-gate garnish clips <i>m</i>	-	16.00	-
18	1 pc	Rear n/s tail-gate lock <i>Del</i>	-	-	215.50
19	1 pc	Rear n/s tail-gate lock catch <i>new</i>	-	-	63.60
20	1 pc	Rear n/s tailgate lock (upper) <i>new</i>	-	-	215.50
21	1 pc	Rear n/s tailgate lock catch (upper) <i>new</i>	-	-	63.60
22	2pcs	Rear n/s tailgate hinges <i>Lower Best.</i>	-	-	120.00
23	1 pc	Rear n/s tailgate striker <i>new</i>	-	-	80.00
24	2pcs	Rear n/s tail-gate number plate lamp <i>new</i>	-	-	120.00
25	1 pc	Rear n/s windscreen moulding <i>m</i>	-	-	150.00
26	1 pc	Rear lock garnish <i>del</i>	-	-	230.00
27	1 pc	Rear wiper motor <i>new</i>	-	-	265.60
28	1 pc	Rear lock assembly <i>Del</i>	-	335	516.50
29	1 pc	Rear windscreen sealant <i>m</i>	-	-	120.00

30	1 pc	Rear tail-gate weatherstrip <i>new</i>	-	-	320.00	+
31	1 pc	Rear end panel <i>Deited</i>	-	-	184.80	✓
32	1 pc	Rear tail-gate 70 KMPH emblem <i>new</i>	-	15.00	-	✓
33	1 pc	Rear reverse sensor <i>new</i>	-	280.00	-	✓
34	1 set	Rear advertisement sticker <i>new</i>	-	250.00	-	✓
		<i>5375.70</i>	Sub-Total:	0.00	377.00	7,402.90
		<i>4838.13</i>		30%	0%	10%
		<i>1970</i>	After Less %:	0.00	377.00	6,662.61
		Labour				
1		To dismantle damaged parts, straighten & welding.		1,200.00	<i>8w</i>	
2		To spray painting.		1,000.00	<i>8w</i>	
3		To remove and replace rear o/s & n/s door <i>fitting</i>		150.00	<i>120</i>	
4		To remove & refit rear o/s & n/s windscreen		220.00	<i>160</i>	
5		To check wiring		80.00	<i>30</i>	
6		To re-seal anti-rust.		80.00	<i>60</i>	
		<i>1970</i>	Sub-Total:	2,730.00		
			Total:	9,769.61		

Chan
 Chan San Choon
 Director
 DipEng, AAE MIMI,MSAE(Aust)

total: 77415.13 Adrian Cj
1/S: 59K. 2/S 30/09/20

06 Days



AL 8778 1999
 24 hr accident call



PAYNOW

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: