



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20010471/QKyd3q2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 17-11-2020



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                 |                |            |
|--------------|-----------------|----------------|------------|
| Insured Veh. | SGA 984Y        | Veh. Inspected | SMJ 3897C  |
| Policy No.   |                 | Coverage (\$)  | 0.00       |
| Claim No.    | CMTD2002812/AGC | Excess (\$)    | 0.00       |
| Assign From  | GRACE TEO       | Assign Date    | 30/09/2020 |

### 2. Vehicle Particulars & Condition

|              |                  |              |            |
|--------------|------------------|--------------|------------|
| Make & Model | HONDA FIT HYBRID | c.c          | 1496       |
| Engine No.   | HIDDEN           | Year of Reg. | 2019       |
| Chassis No.  | GP51338553       | Colour       | WHITE      |
| Odometer     | 98559            | Steering     | IN ORDER   |
| Brakes       | IN ORDER         | Modification | SPORTS RIM |
| General      | FAIR             |              |            |

### 3. Conditions of Tyres

|                |            |          |         |
|----------------|------------|----------|---------|
|                | Size       | Make     | Balance |
| R/H Front Tyre | 185/60 R15 | GOODYEAR | 6 mm    |
| L/H Front Tyre | 185/60 R15 | GOODYEAR | 6 mm    |
| R/H Rear Tyre  | 185/60 R15 | GOODYEAR | 6 mm    |
| L/H Rear Tyre  | 185/60 R15 | GOODYEAR | 6 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

|                |                                       |                 |            |
|----------------|---------------------------------------|-----------------|------------|
| Accident Date  | 25/09/2020                            | Inspection Date | 30/09/2020 |
| Survey held at | 60 JALAN LAM HUAT CARROS CENTRE#05-68 |                 |            |
| Repairer       | MY CAR CONSULTANT PTE LTD             |                 |            |

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**