

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 02 Oct 2020

**Preliminary Advice**

Vehicle No	: SLN8846H	Accident Date	: 29/09/2020
Make	: MERCEDES-BENZ C180	Policy No.	: DMPCSNW00048072001
Assignment Date	: 30/09/2020	Excess	: S\$500.00
Date of Inspection	: 30/09/2020	Est. Duration of Repair	: 5
Inspection At	: YI HENG MOTOR WORKSHOP (HQ) BLK 1 KAKI BT AVE 6 #02-19 SINGAPORE 417883		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)(cost plus 15%)	:S\$	21,815.99	(ESTIMATE \$20,578.59 + SUPPLEMENTARY \$1,237.40)
Revised Amount	:S\$	13,023.60	(INCLUSIVE OF SUPPLEMENTARY & CHECK ITEMS)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	13,023.60	
Lump Sum Repair	:S\$		

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	62,771.00
Salvage Value	:S\$	
Margin for Repair	:S\$	57,229.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : KINDLY APPROVE ON SUPPLEMENTARY & CHECK ITEMS.