

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 01 Oct 2020

Preliminary Advice

Vehicle No	: SLN8846H	Accident Date	: 29/09/2020
Make	: MERCEDES-BENZ C180	Policy No.	: DMPCSNW00048072001
Assignment Date	: 30/09/2020	Excess	: S\$500.00
Date of Inspection	: 30/09/2020	Est. Duration of Repair	: 5
Inspection At	: YI HENG MOTOR WORKSHOP (HQ) BLK 1 KAKI BT AVE 6 #02-19 SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,633.40
Revised Amount	:S\$	6,740.41
Check Items (Estimated)	:S\$	11,279.87
Total	:S\$	18,020.28
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	62,771.00
Salvage Value	:S\$	
Margin for Repair	:S\$	57,229.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :