

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

01-10-20

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
3, ANSON ROAD
#16-00, SPRINGLEAF TOWER
SINGAPORE 079909

ATTN : MOTOR CLAIMS DEPARTMENT

INSURED : MEI PEIPEI
POLICY NO : DMPCSNW00048072001
OD CLAIM NO : SNM20D203587

VEHICLE NO. : SLN 8846H
MODEL : MEREDES BENZ C180

SUPPLEMENTARY BILL

COST PRICE

1) FRONT GRILLE AIR GUIDE	\$	138.00	<i>de ✓</i>
2) FRONT BUMPER BEAM TOP GARNISH	\$	110.00	<i>de ✓</i>
3) FRONT BUMPER RADAR SENSOR CONTROL UNIT	\$	828.00	<i>cut ✓</i>
	\$	1,076.00	
	COST PLUS :15%	\$	161.40
		<u>\$</u>	<u>1,237.40</u>

Yi Heng 2/10/20

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

30-09-20

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3, ANSON ROAD

#16-00, SPRINGLEAF TOWER

SINGAPORE 079909

ATTN : MOTOR CLAIMS DEPARTMENT

INSURED : MEI PEIPEI

POLICY NO : DMPCSNW00048072001

OD CLAIM NO : SNM20D203587

VEHICLE NO. : SLN 8846H

MODEL : MEREDES BENZ C180

COST PRICE

1) BONNET		\$ 1,322.50	Rx
2) BONNET LOCK	2PCS@\$46.00	\$ 92.00	X nn
3) BONNET SPRING	2PCS@\$21.85	\$ 43.70	X nn
4) BONNET STRIKER	2PCS@\$24.15	\$ 48.30	X nn
5) BONNET CATCH HOOK		\$ 48.30	X nn
6) BONNET CATCH STRIKER		\$ 55.20	X nn
7) BONNET HEAT LINING		\$ 161.00	X nn
8) BONNET HEAT LINING CLIPS	13PCS @\$5.00	\$ 65.00	X nn
9) HEADLAMP	2PCS@\$1,955.00	\$ 3,910.00	eng
10) HEADLAMP BRACKET	2PCS@\$143.75	\$ 287.50	eng
11) FRONT GRILLE		\$ 145.00	eng
12) FRONT GRILLE CLIPS	2PCS@\$5.00	\$ 10.00	nn ✓
13) FRONT GRILLE NET		\$ 145.00	de
14) FRONT GRILLE LOGO		\$ 201.25	mis
15) FRONT GRILLE LOGO GARNISH		\$ 85.00	nn ✓
16) FRONT GRILLE CHROME (TOP)	2PCS@\$54.05	\$ 108.10	RH out - LH X ⁿⁿ
17) FRONT GRILLE CHROME (BOTTOM)	2PCS@\$56.00	\$ 112.00	RH out / LH X ⁿⁿ

18) FRONT LICENCE PLATE BASE GARNISH		\$	212.00	<i>m's ✓</i>
19) FRONT BUMPER		\$	977.50	<i>de ✓</i>
20) FRONT BUMPER CLIPS	10PCS@\$5.00	\$	50.00	<i>de ✓</i>
21) FRONT BUMPER TOW COVER		\$	58.00	<i>m's ✓</i>
22) FRONT BUMPER SENSOR (CENTRE RIGHT)		\$	149.50	<i>dis ✓</i>
23) FRONT BUMPER SPONGE		\$	109.25	<i>ona ✓</i>
24) FRONT BUMPER GRILLE BEAM		\$	280.00	<i>ona ✓</i>
25) FRONT BUMPER REINFORCEMENT		\$	281.75	<i>bt ✓</i>
26) FRONT BUMPER REINFORCEMENT BRACKET	2PCS@\$138.00	\$	276.00	<i>X nn</i>
27) FRONT BUMPER LOWER GRILLE		\$	86.25	<i>de ✓</i>
28) FRONT BUMPER LOWER TRAY		\$	145.00	<i>ona ✓</i>
29) FRONT BUMPER LOWER DEFUSER		\$	185.00	<i>ck ✓</i>
30) FRONT BUMPER LOWER DEFUSER CHROME		\$	158.30	<i>ona ✓</i>
31) FRONT BUMPER SIDE ATTACHMENT	2PCS@\$55.25	\$	110.50	<i>X nn</i>
32) FRONT BUMPER SIDE GARNISH	2PCS @\$46.00	\$	92.00	<i>R4-de ✓, L4 X nn</i>
33) PRE COLLISION SENSOR	2PCS@\$120.00	\$	240.00	<i>nn ✓</i>
34) FRONT SUPPORT PANEL		\$	580.10	<i>X R</i>
35) FRONT SUPPORT TOP GARNISH		\$	45.10	<i>X nn</i>
36) FRONT SUPPORT TOP GARNISH CLIPS	6PCS@\$5.00	\$	30.00	<i>X nn</i>
37) AIR-CON CONDENSOR		\$	920.00	<i>dd ✓</i>
38) RADIATOR ASSY		\$	563.50	<i>X</i>
39) WATER COOLER		\$	630.00	<i>X</i>
40) FRONT FENDER	2PCS@\$563.50	\$	1,127.00	<i>X</i>
41) FRONT FENDER INNER COWLING CLIPS	20PCS@\$5.00	\$	100.00	<i>X</i>
		\$	14,246.60	8792.35
	COST PLUS :15%	\$	2,136.99	10111.20
		\$	16,383.59	

SPECIAL NETT ITEM

1) FRONT LICENCE PLATE (EMBOSS)

\$ 55.00 *57-45*
\$ 55.00
45

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM

\$ 80.00 *30*

2) TO APPLY UNDERSEALING ON AFFECTED AREAS

\$ 220.00 *X 44*

3) TO REMOVE/REFIX AIR-CONDENSOR, PIPNG SYSTEM AND TOP UP GAS

\$ 280.00 *100*

4) TO REMOVE/REFIX RADIATOR ASSY & CONDUCT PRESSURE TEST

\$ 250.00 *X un*

5) TO REMOVE/REFIX HEADLAMP CONTROL UNIT AND REALIGNMENT LIGHTING SYSTEM

\$ 280.00 *X un.*

6) TO REPROGRAMME HEADLAMP ASSY

\$ 450.00 *100*

7) TO REPROGRAMME RE-COLLISION SENSOR AND RESET

\$ 380.00 *200*

8) TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC

\$ 1,100.00 *600*

9) TO RESPRAY ON AFFECTED AREA

\$ 1,100.00 *600* 1630

\$ 4,140.00

GRAND TOTAL : \$ 20,578.59

Taufik 97445744

wp

EX: 7500

30/9/20

Compsun

Resun after repair

tepti@khant.com

4-5 days

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10111.20

45

1630

supp 1237.40

13023.60

I/s \$10,400

5 days