



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBM9980U YAMAHA Y150 REPAIR ESTIMATE (01/10/2020)

ITEM DESCRIPTION	AMOUNT SGD
1 FRONT WHEEL	\$320.00 ?
2 FRONT BRAKE DISC	\$145.00 ?
3 FRONT FORK ASSY RH & LH	pluck \$360.00 bl-
4 STERING STEM	\$145.00 bl-
5 CONE BEARING SET	\$60.00 na-
6 FRONT FENDER	\$65.00 cut-
7 FRONT SHIELD	\$95.00 cut-
8 STAY . FRONT SHIELD	\$58.00 ?
9 HEADLAMP ASSY	\$145.00 ant-
10 HANDLEBAR TOP COVER	\$45.00 ant-
11 HANDLEBAR FRONT COVER	\$28.00 X
12 HANDLEBAR REAR COVER	\$28.00 X
13 IU UNIT	\$160.00 ?
14 IU BRACKET	\$60.00 ?
15 HANDLEBAR	\$75.00 ?
16 SIDE MIRRORS	\$90.00 cut-
17 PILOT LIGHT	RH-? \$250.00 LH-cut-
18 PILOT LIGHT CASE	RH-cut \$60.00 LH-cut-
19 FRONT SIGNAL LH	\$60.00 cut-
20 FRONT FAIRING LH	\$95.00 cut-
21 GEAR PEDAL	\$35.00 bl-
22 ENGINE COVER	\$115.00 did-
23 GASKET X1	\$12.00 na-
24 ENGINE OIL	\$20.00 rec-
25 BACK SHIELD UPPER	\$65.00 ?
26 LOWER SPOILER LH	\$35.00 X
27 FRONT FOOTREST BAR	\$75.00 bl-
28 FRONT FOOTREST ASSY COMPLETR LH	\$60.00 did-
29 SIDE STAND	\$28.00 X
30 MAIN STAND	\$75.00 ? pluck
31 REAR TOP BOX	\$580.00 cut-
32 TOP BOX BRACKET	\$140.00 ?
33 CAP EXHAUST	\$28.00 cut-
34 HEAT PROTECTION	\$38.00 cut-
35 EXHAUST ASSY	\$390.00 fixed dd-
36 GASKET X1	\$6.00 ?
37 FRONT FOOTREST RH	\$60.00 did-
38 BRAKE PEDAL	\$75.00 Ry
39 FRONT SIGNAL RH	\$60.00 cut-
40 BRAKE LEVER	\$18.00 cut-



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263

Ubi : Bk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250

FBM98800 YAMAHA Y150 REPAIR ESTIMATE (01/10/2020) 6515 0770 Fax: (65) 6515 0779

Website: www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

ITEM DESCRIPTION

AMOUNT SGD

41	REAR SIDE FAIRING	\$115.00 <i>act</i>
42	TRANSPORTATION TP-IDAC-BIKESHOP @\$50	\$100.00 <i>80</i>
43	WORKMANSHIP TO REPLACE DAMADGE PARTS	\$350.00 <i>250</i>
44	BODY CHASSIS REPAIR	\$450.00 <i>200 plus?</i>
45	TRANSPORTATION 2WAY TO REPAIR CHASSIS @\$50	\$100.00 <i>80?</i>
46	STICKER SET	\$120.00 <i>re</i>

TOTAL \$ \$5,494.00

Tanji 97495749
'wp' 01/10/20 @ 420 per
2 am psun
Resurvey after repair.
4-5 days
Tanji @ 11hantian.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: