



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0710/2020/NS
DATE : 30-Sep-20
WIP : 51284

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR CHONG GUAN KEAT
ADDRESS : 130 SERANGOON AVE 3
#11-05
SINGAPORE 554479
TELEPHONE : HP +65 90046726
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900084874-01
VEHICLE NO : SKL 3323 E
MODEL CODE : AUDI A5 SPORTSBACK 2.0 TFS
MODEL YEAR : 9/4/2019
ENGINE NO : CVK 076864
CHASSIS NO : WAUZZZF59KA029348
MILEAGE : 27538KM
DATE IN : 29-Sep-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Sep-20
PLACE OF ACCIDENT : ALONG CLEMENTI AVE 6 BEF CLEMENTI LOOP



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 3323 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00	✓
3	TO RENEW REAR WINDSCREEN TO FACILITATE REAR LID RENEWAL.	S/N \$ 480.00	✓
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$ 400.00	✓
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	150
SUB TOTAL LABOUR CHARGES		: <u>\$ 1,720.00</u>	



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 3323 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISLODGE ROOF LINING TO FACILITATE RENEWAL OR REAR LID HINGES.	S/N \$ 280.00	X
7	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 480.00	X
8	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,500.00	1000
9	TO RESPRAY REAR BUMPER, REAR LID, HINGES AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 2,750.00	1100 1650 H.S.
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,922.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 3323 E

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR BUMPER <i>Rehd</i>		\$ 2,504.00 ✓	2003.20
2 REAR BUMPER FIXING PARTS <i>new</i>		\$ 163.00 ✗	
3 REAR BUMPER SECURING STRIP <i>new</i>		\$ 220.00 ✓	176.00
4 REAR BUMPER CHROME TRIM <i>new cruled</i>		\$ 1,005.00 ✗ ✓	804.00
5 REAR LIGHT REFLECTOR - LH / RH <i>new</i>	2	\$ 82.00 ✗	
6 LED TAIL LIGHT - LH / RH OUTER <i>cut</i>	2	\$ 2,258.00 ✓	1806.40
7 TAIL LIGHT TRIM - LH / RH OUTER <i>Rehd</i>	2	\$ 60.00 ✓	46.72
8 LED TAIL LIGHT - LH / RH INNER <i>cruled</i>	2	\$ 2,016.00 ✓	1612.80
9 TAIL LIGHT TRIM - LH / RH INNER <i>Rehd</i>	2	\$ 60.00 ✓	46.72
10 LED LICENSE PLATE LIGHT <i>cruled</i>	2	\$ 100.00 ✓	79.52
11 ADDITIONAL BRAKE LIGHT <i>Day 2</i>		\$ 570.00 ✓	455.60
12 REAR PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	TBC ✗	
13 REAR BUMPER CARRIER <i>Not new</i>		\$ 886.00 ✗	
14 REAR BUMPER CARRIER SEAL <i>Not new</i>	2	\$ 28.00 ✗	
15 REAR BUMPER GUIDE SECTION - LH / RH <i>Not new</i>	2	\$ 44.00 ✗	
16 REAR LID <i>Rehd</i>		\$ 3,080.00 ✓	2464.00
17 REAR LID HINGE - LH / RH <i>Not new</i>	2	\$ 452.00 ✗	
18 REAR LID ATTACHMENT PARTS <i>Not new</i>		\$ 152.00 ✗	
19 REAR LID LOCK <i>Rehd</i>		\$ 241.00 ✓	192.80
20 BONET LOCK COVER <i>Not new cut</i>		\$ 12.00 ✓	9.60
SUB TOTAL SPARE PARTS	:	\$ 13,933.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 3323 E

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	REAR LID FLAP GASKET	<i>Nec</i>	\$	234.00	✓ 186.80
22	LID LOCK PUSH BUTTON	<i>cracked</i>	\$	1,330.00	✓ 1064.00
23	REAR LID STRIKER PLATE	<i>Nec</i>	\$	63.00	X
24	REAR LID SERVOMOTOR	<i>Nec</i>	\$	291.00	X
25	REAR LID DRIVE UNIT	<i>Nec</i>	2 \$	3,584.00	X
26	REAR LID BOWDEN CABLE	<i>Nec</i>	\$	57.00	X
27	PACKING ADHESIVE	<i>Nec</i>	\$	18.00	✓ 14.40
28	AUDI EMBLEM	<i>2</i>	\$	138.00	✓ 110.40
29	A5 INSCRIPTION	<i>1</i>	\$	95.00	✓ 75.36
30	REAR WINDSCREEN	<i>Nec</i>	\$	1,155.00	✓ 924.00
31	PRIMER	<i>Nec</i>	\$	19.00	✓ 14.96
32	REAR CROSS PANEL	<i>Dented</i>	\$	356.00	✓ 284.40
33	CROSS PANEL REINFORCEMENT	<i>Dented.</i>	\$	625.00	✓ 500.00
34	REAR LID TRIM PANEL	<i>cracked</i>	\$	441.00	✓ 352.80
35	REAR CROSS PANEL TRIM	<i>cracked.</i>	\$	356.00	✓ 284.80
36	BOOT LID CONTROL UNIT	<i>Nec</i>	\$	399.00	X
37	REAR NO PLATE	<i>at</i>	S/N	TBC	✓ 80.00
38	REAR WINDSCREEN SEALANT	<i>Nec</i>	S/N \$	200.00	✓ 200.00
39	STONE CHIP	<i>2</i>	S/N \$	180.00	✓ 180.00
40	CAVITY WAX	<i>1</i>	S/N \$	140.00	✓ 140.00
41	ACRYLIC SEALANT	<i>1</i>	S/N \$	180.00	✓ 180.00
42	SUNDRIES	<i>Nec</i>	\$	350.00	✓ 77.60
TOTAL SPARE PARTS			:	\$	24,144.00
TOTAL LABOUR CHARGES			:	\$	8,922.00
GRAND TOTAL			:	\$	33,066.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adrian Lj

SURVEYED DATE

: 30/09/20

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

: Not Authorised, 05 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

CST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0710/2020/NS
2-Oct-20
Glory Tan
1 of 2
SKL 3323 E
AUDI A5 SPORTSBACK 2.0 TFS

Quantity	Description	Unit Price	Amount
Parts			
1	Rear fender reinforcement for D-pillar RHS } <i>Painted</i>	\$ 271.00	✓ 216.40
2	Rear fender reinforcement for D-pillar LHS } <i>Painted</i>	\$ 271.00	✓ 216.40
3	Rear fender inner side panel RHS } <i>Buckled</i>	\$ 203.00	✓ 162.40
4	Rear fender inner side panel LHS } <i>Buckled</i>	\$ 203.00	✓ 162.40
5	Taillight panel RHS } <i>Buckled</i>	\$ 162.00	✓ 129.20
6	Taillight panel LHS } <i>Buckled</i>	\$ 162.00	✓ 129.20
7	Luggage compartment trim LHS <i>compd</i>	\$ 1,034.00	✓ 827.20
Labours			
1	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	s/n \$ 1,400.00	✓
2	To carry out first measurement on car-o-liner.	s/n \$ 800.00	✓
3	To put on vehicle on car-o-liner to facilitate the repairing of the rear portion.	s/n \$ 1,800.00	✓
4	To cut out and weld both taillight panels, both rear fender inner side panel and both rear fender reinforcement.	\$ 6,000.00	3000
5	To respray both taillight panels and spare wheel housing.	\$ 2,000.00	1100
TOTAL		\$ 14,306.00	

Adrian Ling
05/10/20
Add
07 Days
SLS



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

ST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0710/2020/NS

Date

20-Oct-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SKL 3323 E

Model No

AUDI A5 SPORTSBACK 2.0 TFS

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To install sticker for rear bumper chrome trim. <i>new</i>	s/n \$ 200.00	✓ 60

TOTAL

\$ 200.00

*Resigned
21/10/20
Adrian
[Signature]*