

AG - (PIP) JM

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 30.09.2020
Time: 14:41:09
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305425376
REGN NO : SHC 307E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 12.03.2019
DATE/TIME IN : 30.09.2020 11:20
ACCIDENT DATE : 29.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52	Ans ✓
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	Ans ✓
0003	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	22.00	20.00	17.60	Ans ✓
0004	04-01-0104-2544-G	IONIQVC CAP-RR HOOK	1	98.80	20.00	79.04	X
0005	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	135.70	2.00-	135.70	Ans ✓
0006	04-01-0104-2288-G	IONIQVC BEAM-RR BUMPER	1	294.80	20.00	235.84	?
0007	04-01-0104-2532-G	BRACKET ASSY-RR BUMPER SI	1	55.80	20.00	44.64	?
0008	04-01-0104-0852-G	REFLECTOR/REFLEX ASSY-RR	1	31.90	20.00	25.52	Ans ✓
0009	04-01-0104-2270-G	IONIQVC EMBLEM-HYBRID	1	24.30	20.00	19.44	Ans ✓
0010	04-01-0104-2271-G	IONIQVC EMBLEM-IONIQ	1	31.30	20.00	25.04	Ans ✓
0011	28-01-0103-0009-A	(I40)REAR BOOT LOGO CCTPL	1 N	30.00	2.00-	30.00	Ans ✓
0012	28-01-0103-0010-A	(I40)REAR BOOT TEL NUMBER	1 N	30.00	0.20	30.00	Ans ✓
0013	28-01-0103-2014-A	I40V3 APP LOGO REAR DOOR	1 N	40.00	0.02-	40.00	Ans ✓

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305425376
 REGN NO : SHC 307E
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 12.03.2019
 DATE/TIME IN : 30.09.2020 11:2
 ACCIDENT DATE : 29.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,411.34

JOB NATURE

0000 PB	PANEL BEATING	700.00	480
0001 SP	SPRAYPAINT CHARGE	500.00	400.
0002 17-01	CHECK ALL LIGHTING	50.00	30.
0003 20-05	RENEW ADVERTISEMENT STICKER-BOOT		100.00 ✓
0004 L	REMOVE/REFIX REVERSE SENSOR ASSY	80.00	30.
		SUB-TOTAL : 1,430.00	

TOTAL : 2,841.34

MVA NAME & SIGNATURE

DATE:

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE:

Tamplin 97495749 Westlake
 'WP' 30/9/20 @ 4pm 2-3 days
 P/P before paint
 tamplin @ lkk auto-con

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date/Time: 30.09.2020 13:54

Page : 1

Team:

ARC Repair TP(CFS0)1

JOB CARD Sales Order:

JC NO.:305425376

CUSTOMER

CITYCAB PTE LTD
CUSTOMER NO. 7010070
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65551188 (O)

IDENTIFICATION CARD NO.

REGN NO: SHC 307E	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 30.09.2020 11:20
YR OF MANU. 12.03.2019	TARGET DATE
CHASSIS CODE KMHC851CVKU134451	COMPLETION DATE/TIME:


Accident Date: 29.09.2020
NATURE: 3P 29.09.2020

JOB DESCRIPTION

/NO

LABOR CODE

DESCRIPTION



& PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Payment Slip

SHC 307E

JU AIG

Service Advisor

Handed to Service Reception upon collection

Signature/Date

Exit Pass

Vehicle No.:

SHC 307E

Name of Service Advisor

Date