



CENTRAL AUTOMOTIVE PTE LTD

1 Sunway road #08-44 Easdash@Sunway
Singapore 677615
Tel: (65) 6352 4628 Fax: (65) 6352 5541
RCB No: 2019075JOC

ESTIMATION QUOTE

FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : YQ1638T
MAKE MODEL : HINO XZU710R
REFERENCE : CTA-202009-02
DOA : 18-Sep-20
CLAIM TYPE : TP CLAIM

PAGE 1 OF 1

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
FRONT BUMPER	1	\$ 720.00	de ✓
FRONT HEAD LAMP ASSY (RH)	1	\$ 580.00	ap ✓
FRONT SIDE PANEL (RH)	1	\$ 320.00	ant ✓

SUBTOTAL \$ 1,620.00
BALANCE C/F \$ 1,620.00

ADDITIONAL ITEMS	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 1,620.00	
LUMP SUM LABOUR TO REMOVE AND INSTALL ALL ABOVE ITEMS INCLUDING TOOL AND MATERIAL	1	\$ 600.00	400
DRIVER RIGHT DOOR & REALIGNMENT (DOOR ARM SPRING REPAIR, REMOVE GLASS PANEL, SWITCH, ARMS, INSIDE PANEL, PANEL BEATING AND REFIX)	1	\$ 680.00	200
RESpray DOOR AND TRUCK CABIN	1	\$ 1,200.00	600
ARTWORK FOR TRUCK CABIN	1	\$ 280.00	180

SUBTOTAL \$ 2,760.00
BALANCE C/F \$ 4,380.00

MISC	QTY	LIST PRICE (\$)	REMARKS
BALANCE B/F		\$ 4,380.00	
LOSS OF USE - REFRIGERATED TRUCK RENTAL (\$320 X 5 DAYS)	1	\$ 1,600.00	
LTA SEARCH FEE	1	\$ 7.45	

\$ 1,607.45
GRAND TOTAL \$ 5,987.45

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts price are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495749 / 167418434

- WP' 26/10/20 C / pm

04 days

tanpin@lkkauto.com

Lumpsum, Resurvey after repair.

Mr Wee. 97907149